1/4 CORNER 10-25-79 CIM 33-34 DOVER 106-11 1/4/83 set 1" sq pipe/cap #613406

GOV. NOTES - 1855 J BALL

SET 1/4 SECTION CORNER post m+l 40 lks 2640

drove charred stake

NO KNOWN RECORDS OF CORNER

10-4-1979 1/16th South: Dug with the backhoe centered on a point, taken in line with the fence East (now gone) and in ℄ CR 10 as measured in in 1976, West 2½', East 3½', North 5', and South 5', by 6½' deep to clay. The oldest road was worn into the clay. Found nothing

10-25-1979 Set a ⊙CIM over a 5/8" x 20" iron 9.0 South of POT (2653.57 N of S.33-34) on the line from S 33-34 to the CHD corner location at Sec. Cor. 27-28-33-34. This location chosen N-S because (1) it is an average of the ¼ lines across Secs 33 & 34

(2) ℄ line with old fence ridge East which also corresponds with 1935 C.H.D. topo. call for fence East here.
The location chosen E-W to hold the 1/16th fence East & West. Corner in ℄ C.R. 10.

RP's: C.S Disc in power pole NW 59.29
C.S Disc in power pole SW 117.80
Punch hole in top center 24"
C.M.P. (N. end) NW 41.51

5/8" rod 17½ E. of ℄ of C.R. 10 NE 28.27 Cone 1983

6-26-82, ¼ Cor 33-34: Checked RP's to CIM

1-4-83 gone → - C.S.D. in power pole NW 59.29
- Punch hole in top Center 24" C.M.P. (N. end) NW 41.52

Took RPs 5/8" rod 17½' East of ℄ of C.R. 10 NE 28.27

1-4-83, ¼ Cor 33-34: Set a 1" sq. w/cap 0.3' East of ℄ Concrete of C.R 10. Took no new RPs. Drilled Coin and set CIM. Set Brass over it.