X 9-5-1975 Set 16" CIM over ½"x 30" rod – in Spot in Clay & Glass & pottery found. ①

¼ Corner south ¼ 35 Dover 106-11
north ¼ 2 Elmira 105-11.
#613504

11-1891 Thos Fraser P462 No 446 & 2 Julius Kemp. Corner gone for 25 years. NEBT still standing, but marks gone. Mr Bolen & others aver marks were once plain on this tree with blaze marks plain set stone 3 x 8 x 24. in accordance with govt field notes from B tree

– 1/16 west – fence running south plain on former survey Meas. 20.00½

– Meas west to sec corner 40.03½4

Gov.'T notes: 1853 - Set Post for 1/4 Sec. Corner
B.T.'s Burr Oak 5" N 33°E 64 links
Burr Oak 8" S 17°W 252 "

9-2-75 Dug with backhoe to clay. Road had been cut to clay. Found broken glass and pottery 3' deep and in the clay but could find no mark of stone

9-5-75 Set C.I.M. over ½" x 30" at 9-2-75 location.

R.P.'s

CS.D E side power pole NW 50.82
CSD E side corner post S 32.42
⅜" x 30" rod on W. side fence S S.67.0
Corner 2' S & road E and 1' W & road N.
and in line with fence S

S ¼ 35 106-11
N ¼ 2 105-11

#613504 (2)

7-22-98
Found CIM in Good Condition Down 0.4'
1'W & TWP RD (185th Ave SE) N
3'S & E-W TWP RD (60th St SE)
CSD E Side Power Pole NW 50 84

"613504" D

7-22-98
EPA 22 53

SOUTH 1/4 39 106-11

NORTH 1/4 2 105-11

FOUND CIM IN GOOD CONDITION DOWN 0.4'

1' W ℄ TWP RD (185TH AVE SE) N

3' S ℄ E-W TWP RD (60TH ST SE) 9-2-75

C.S.D. E SIDE POWER POLE NW 50.89 50.82

NEW RP C.S.D. E SIDE CORNER POST S 32.03

1975 CP GONE. REPLACED SINCE 1975