#613506 (1)

/

¼ corner 34-35 Dover 106-11.
11-1891 Chas Fraser. P462 No 446 & 2 Julius Kemp.
Corner used in establishing NW Cor 2, 105-11 P462
found iron by foot of post which is corner of fences
N-E-W set by Olds & Keyes in former survey,
claimed by Keyes as set exact point of orig.
govt stake - no means to see cor.
GOV. NOTES - 1853 - J BALL
SET ¼ SECTION CORNER POST MTL 40 chs 2640
6" burr oak N 66 W 23 LKS 153.8
CORNER NOW ON E-W FARM BOUNDARY LINE, COMMON LAND
ON N & S SIDES OF CORNER
CORNER IN highest land IN AREA, LEVEL AND WIDE
CONTOURS

8-19-1980 ¼ Cor 34-35: Chained from iron traverse pt. East 675 ± to ⅛4 fence North, then 662 ± to ⅛16 fence South. We wanted to look for the corner from 12' to 16' East of the t.p. and under the E-W fence but two large boulders had been pushed in here



We dug off the top foot of soil along the south edge of the boulders and dipped for T. Fraser iron but could find nothing, but just between the boulders and about ½' South of the fence struck a 4" x 5" x 12" stone standing. Removed the stone and found it to be on the So. edge of a post hole running well down into clay. Scraped to bottom of post hole and there was bits of rusty wire but could find no particular rust hole from fraser iron

(cont.)

¼ Corner 34-35 Dover 106-11 #613506 (2)

8-19-1980 Continued: This is the only spot we dug to clay. Drove the bottom post of a steel fence post at the post location and set the stone along side. This spot appx 9' South & 14' East of the traverse point. Must shoot from South after the monument set.

80. (613506) D 11-23-98
MW EA

1/4 Cor 34-35 106-11 Dover
Found steel Fence post
bottom set in 1980 at
Post & Stone location
Fd. and used by GGG
recently with their Fiberglass
Post beside. Set CIC/P2
at this Position The corner
Falls 1' South of Main Fence
line E-W and between two
large boulders East & West
Set Survey Sign & Post 1'
South of Monument with
Firberglass post beside Monument.