/ 9-2-75 Set C.T.M. over stone #613605 #1

section corner south 35-36 Dover 106-11.
north 1-2 Elmira 105-11

6-1880 John Fraser P366 No 357 L36 town boards corner in long dispute when records were scarce & mostly found L W B tree & other B T remains set stone 2"x8"x24" with tan oak stake by side.

8" black oak N 54°45' W 80½ lks
tree L 44°30' E 28½ lks

-1/16 east - set stone 2x16x20 M & L 19.95½ (1317.03)

4-1892 2 hos Fraser P476 No 455 L1 M Hayes.
found stone with stake by side, undisputed -

over)

This corner claimed set in place for govt state.

5-1900 Robt Fraser P674 No 599 S1 F cornwell.

John Hayes

found long limestone on north side road,
claimed by all parties as true corner
- 1/16 east found boulder stone avered by Mr Robinson
as corner he helped John Fraser set - no mear
- south set 1/16 stake pop mear 20 & 3 1/2

11-1891 Thos Fraser P462 No 446 S2 Julius Kemp

found stone set by John Fraser & NW B tree.

40 01 west to stone - 39.58 each to stone

Gov't notes: 1853 Set Post
Bfs Burr oak 10" S 2 1/2° E 40 links // Burr oak 11" N 8° W 160 links
Burr oak 12" S 74 1/2° W 134 " Burr oak 14" N 53° E 164 "

#613605 #2

Section Corner South 35-36 Dover 106-11

North 1-2 Elmira 105-11

9-2-75 Dug with backhoe and found recorded limestone with broken glass (pottery) around and stake on S side (removed to office) 3' deep in ℄ of E-W twp. road. Set 1" x 30" shaft in stake hole. Set scrap iron around stone and ½" rod on W. side. Set C.I.M. over ½" x 12" rod over stone. Corner lies 1' W of fence S and in line of fence N.

R.P.'s Disc in corner post North 25.11

Disc in corner post South 33.60

Spike and Disc in 12" white Oak SE 76.25

9-3-75 (1/16 E) Dug with backhoe at 90th Transit measure from N. Sec. Cor 1-2 and on line to NE 1 Found stone 2"x15"x12" (broken if 2x16x20 recorded stone) but could find no mark.

7-[redacted]-98
Found CIM Down 0.3' with Head Broken off and Leaning Badly to the East

7-21-98
Removed old 20" CIM To Place New One. Dug down to ½"x12" Rod over stone. SET 16" CIM. Down 0.2' Falls in G. E. W THP RD 1' West Fence line south And IN LINE of Fence North CSO in CP Leaning East N 26.67

52

"613605" E

7-21-98
EPA LL

✓ SECTION CORNER S 35-36 DOVER 106-11
N 1-2 ELMIRA 105-11

7-17-98 FOUND CIM DOWN 0.3' WITH HEAD BROKEN OFF AND LEANING BADLY TO THE EAST.

7-21-98 - REMOVED OLD 20" CIM TO PLACE NEW ONE. DUG DOWN TO ½" ⌀ 12" ROD OVER STONE. SET 16" CIM. DOWN 0.2' FALLS IN ℄ E-W TWP RD 1' WEST FENCE LINE SOUTH AND IN LINE OF FENCE NORTH CSO IN CP LEANING EAST N 26.67