1 9-18-73 Set CIM over RR spike and stone. (1)
Cert 4-15-75 9/28/92 Set CIM over CIM

section Corner 1-2-11-12 E yoke 106-12
#620105.

6-1874 Hunter P247 No 248 & 2 P Brockway.
found stone set by adjacent land owners when
orig corner stood B tree gone.
– Meas north 40.10 2646. stake by fence corner.

6-1875
10-1877 Hunter P281 No 278 & 12 Dr & Teal, John Buck.
found stake set on top stone P247.
1/16 east set stake N & L 19.86 1/2. to stake at N 1/4 12 set N & L.
above 1/16 set for line south also 1311.09 a stake set 50 lks south on line.

9-18-73 dug in center road on line fence north, found
L stone tapered to chisel point 4" wide x 12" at bottom
tapered to perfect pyramid 2.9' deep 3' south center road.
4' west of fence running north placed track and glass
by stone with RR spike letter stone and C/M.
Meas E to 1/4 1-12 found. 2621.8 then 2621.8 to Sec Cor.
1/4 corner 1.0' south of direct line.
51.25 6' W of S to 20 D nail W side blazed 18" Multiple Br O.
139.4 SE to NW corner glazed brick bone
145.0 ENE to cone nail on SSE side BP 38172

---

set by William Jones 9-1853
40.00 set a post at qr sec corner deposited charred stake,
made mound trench & pits planted cherry seeds SW & NE
Red Oak S 11 W 12 E 25
Red Oak S 5 22 E 32 & made trench
Red Oak 4 N 82 W 21

#620105 (2)

SECTION CORNER 1, 2, 11, 12 E40TA 106-12
9/28/92 County Surveyor found C/M
21" deep in E-W rd, the road was
regraded a couple of years ago according
to adjacent land owner, it seems to
have moved north a little. Set C/M over C/M
℄ E-W twp rd North 6'
℄ Farm drive South, East 36'