/ 5-11-92 set CIM over orig stone & iron. #620205 (1)

section corner. 2-3-10-11 Ejota 106-12

10-1872 Hunter P209 no 217 S10 H Harbert N Cor M Bowler

Corner gone, dug over large area

set corner 2 rods from south road fence.

and same distance east of N 1/4 10 as N 1/4 10 is

east of N W cor 10 39.99.

- meas south to E 1/4 10 40.06.

6-1874 Hunter P247 no 248 S2. O. Brockway.

found stake set P209. no meas.

6-1893 H Fraser P511 no 479 S10 Smith, Munkey Ops.

found stake set by Hunter P209.
set stone 4x12x15 in place of stake.

-1/16 west set stone 3x12x15 M&L 19.98½. 1319.01

3-31-71 Co surv. found 1" iron in center road on line N-S fences.
Likely set in Sankstone survey of section 10.
- meas west from iron R 1319.01 Otto eyeball line of fence north
1321.2 - eyeball line of fence south 1652.6. property line
- center pavement Hwy 42. and of road east 2637.8 R 2638.02

5-9-72. Co surv dug with Co Hwy Dept backhoe. ground
frozen super hard below 30" road work to clay by Hanks
walnut road. had taken corner & reset by testimony and fences.
- found top of limestone exact size recorded set 1"x10"
iron on south side (sankstone cor) corner 3.2' down
(±2' N. of Sankstone cor)

see Card # 2.

#620205 (2)

Card # 2. 2-3-11-10 Eyola 106-12.

5-9-72 Cont - did not set discs as time short as was going to try for 1/16 stone west while backhoe here below are RP to Sandstone iron and stone found.

Checked RPs 5/83

(Sandiron 44.83 / Stone 82.88)

46.17 to RC Cap L.E. on NE side PP # 38181.

84.95 to Pipe Cap L. on E side trans PP (no number

- Meas south to nail set 8' west assumed 1/4 10-11. 2642.6 from stone as found to nail meas carefully (not fly)

5/88 CJD E side fe. post in ditch N 27.39

5-11 found meas west to 1/16 1316.97.

final meas South to 1/4 10-11 as set 2639.74

9/28/92 County Surveyor fd cors in good cond.

over 1/16 west

"1/16 stone" mark set by 21 Fraser. 3x12x15 M&L 1319.0.
- found stone easily over 3' deep. - set 1¼x2' pipe at corner
over stone & punk. - 1.5 ℄ road 20' E fence north.
54.62 NE to pepsi cap on SE side PP # 38187.
34.05 N to pepsi cap on E side new corner post
℄ fences running N & W.
42.35 SE To Center ℄ end buried road culv.

eyeball meas of property fence running south 1650.25 from CIM

---

set by William Jones 9-1853

80.00 Set post at corner to sections 2, 3, 10 & 11 deposited handful Char coal made mound trench & pits & planted cherry seeds S.E. & N.W.