#620409

1

1/4 corner center 4 Eyota 106-12.

5-1903 C Armstrong P46 B. S 4 A Randall etal.

set oak stake at inters right lines.

36" willow S 12° E 34 or 39 links.

– set oak prop cor stakes for lines south.

– east 8.21 then 11.71 to 1/16 cor then 19.92 to E 1/4

– west 6.20 (409.2) then 9.98 (658.68) then 23.71 to 1/4 cor. (1564.86)

4-26-71. set temp mark as 00 for 1/4 4-5 in low fence west which came. 3?.0 west of staple in barb-wire in corner post east some 3' above ground. Near line east Carefully

over

found positive fence line south R 1564.86 A 1567.7
" " " " " R 2223.54 A 2226.7
found fence line north (spoiled wood stake set in
6-1970 to help find N¼4 at 2644.0 R 2632.74
pulled spoiled stake, drove down to 3" up in line main fence
west at 2637.0 from Ł road west R 2632.74
overrun over record near .16' per 100' W¼4 (Ł) to center (tie)
" " " " .17 " " SE 4 (elm) to S¼5 fence line
" " " " .153 " " W¼4 4 (fence) to SW 9 (rod)
at center drove 12" oak machined spool from old furniture
piece up 2" with glass (blue) broken around it as center
by line fence west and meas from west at 2637 and leaning
huge willow in place in 5-1903.
- Nail in top leaning willow SE 23.0
- Blazed 10" soft maple in fe Ł North NE 11.0
- Main line fence north E 7.0 Actual wire N 4.0' fat Main line due west