~~5-27-64 set C/M over 1/2" x 2' rod~~ #620605 Carda (1)

11-3-70 Found stone and 8-24-73 Set C/M on stone 20-14-14-4
6-16-87 correction ~~Corner~~ Reset 8-24-73
section corner West 6-17 Elgin 106-12
east 1-12 Marion 106-13.

5-1871 Hunter P184 no 195 L6 W & S. Elliot
found stone in center road axeed planted by Mr Kyslop.
when orig corner stood. 1220.34 1317.36
- 1/16 east set stake on line 18.49 - then 19.96 to stake 2537.7 total
in mound & pits. line 8 links short

5-1883 Hunter P382 no 373 L7 H Morse etal.
found stone in center road P184. (2537.7)
- Meas east to fence line north (corner destroyed 38.45
(over)

– meas south to RR tracks (likely ℄) 24.73 (1632.18)
℄ could be 24.72

See Card 3 Larson 1910.

5-1964 J Kerr. B 89 P69 Earl white 1632.18
29

meas from center rail road tracks Hunters distance
could find nothing - came on south shoulder road
edge traveled surface of road - found wires S & N + some
a little beat fence line south. stone
set C I M over ½" rod. ~~fence south~~ no ant.
meas east to fence north - 2536.34 R 37.7. corner

This corner always in center road which I believe
still is in center road despite meas to RR. there
rails have shifted to other place. (corner in doubt)

Dec PP SSE 18.1 Meas - south 26 29.04
SW corner barn. NE 95.6. meas north 26 54.0
another reason to doubt corner.

#620605 (2)

Card # 2. West 6-9 Eyota 106-12.
East 1-12 Marion 106-13.

5-1964 JKerr B 89 P29 details of search for corner. found some wires & fences and small boulders in south shoulder road. very near Hunters near to property lines east and center railroad south - over 10' south center road which always plainly stated as corner location. As yet had not run east line of section 12, setting E¼ 12 M&L 2629.04 about 2640 brg by Hunter and ch Larson which may not be too far off. If NE12 more E center road.

11-3-70 Co Surv - McGhie crew dug from E road south 4' wide, road fill near 2' then hard gravely surface, 10" ± dark iron spotted soil (long time wet) then clean clay. soil very wet at this time. Found small boulder (only one bigger than a fist) in SW corner of digging 4"x6" came N 6.7' and .9' E of C/M as set. stone could not have set this way by nature and dark soil showing slight digging at bottom, small stone directly under but this could (con have been a natural small stone. set ⅝"x2' rod to hold corner

RP to ⅝" rod. Left CIM as is, very wet day.
Disc on W side PP# 21440 up 2° 'E of S 24.4
Pepsi cap on E side old tele pole NW 47.3
SE corner Conc blocks & new milk house NE 67.1
Corner lies 4± 'S & road 7.0' W fence line S.
Meas now 2644.6 to old post in fence corner at W¼ 6
" " 2635.74 to CIM set as W¼ 7 by M & L.
this W¼ 7 only .17' S. of direct line from W¼ 12 over center 12 Marion Forks set by Larson (or found) when it was 2640 north to NE 12 which moved bring corner in exact center road and make meas north 2640 – stone accepted as corner and ¼ 1-12 reset to correspond with it. – also proved Larson used corner 10' south of present CE on 12.
– 5280.34 from CIM W¼ 7 to post found at W¼ 6. indicating still that & road as is (Local farmer where & fence moved.) is correct – if corner moved 4.6 north & rod & put on true line it would be Midway W¼ 7 & W¼ 6 2640.08½. & be in exact & road

Card # 3 W 6-7 Egota 106-12 #620605 (3)
E 1-12 Marion 106-13

12-1910 Ch Larson P 142 B L 12 Thos Fraser.
found boulder corner.
- meas west 40.00 to boulder found then 40.00 to iron set.
- meas south 40.00 to nothing then 40.00 to nothing (set stone)
only help of this survey is that stone actually found at NE 12
and present C/M at E¼ 12 only .17' S of direct line of W¼ 12
over center 12 set by Larson so should not be moved
regardless of NE 12.

5-1971 co surv. located iron for Dashow. at same time pulled
C/M on S side road.
8-24-73 still believe corner should be in center road.
4.6 N of rod should dig east & west 6 or 8 feet. (over

8-27-73. dug with back hoe from 2' east of fence south to 6' west over 4' wide and probed over 3' in all directions - top of road down about 14" with that much good dark soil to clay fairly clean and easy probing. sub-soil has stone of all sizes but in all clay.
- Corner gone if different than corner now in use accepted corner axis set C/M on stone direct no rod below. Corner final-case closed. set C/M in black top just below surface.

Gov. Notes 1853 Oct. Ball, Dep. Sur.
North between 7 and 12.
80.00 Set post and built mound with trench.

#620605 (4)

West Section Corner 6-7, Eyota, 106-12
East Section Corner 1-12, Marion, 106-13

7-7-1982, West 6-7: Dug West from a point 5' South and 2' East of the CIM in place (Hunter's meas. from RK) Found much wire and several boulders as Ken described that had been dug around just South of the location Ken set his monument. We also found a post hole a little further West of this with piece of wire, glass, and a 1½" x 17" x 14"/10" shattered limestone lying along side. post hole } 11.0E 17.5S.

Dug from a point 9' North of the CIM in place (Hunter's meas. from the 1/16 Th. So) West and South. Found a pointed boulder with a 7" x 11" base x 15" long standing and dug well into clay. Dug around but could not find any stake. Put piece

of CIM and piece of blacktop around stone. This stone 8.57 North and 2.73 West of the CIM. Did not yet remove CIM. locals ENE 9.75 SSE 16.7

6/16/84 W 6-7 EYOTA SET CIM OVER 3/4" RE-ROD AT LOCATION OF STONE BOULDER (FD 7/7/82) REMOVED CIM SET 11/3/70 WHICH WAS 8.57 So. & 2.73 E [redacted] CORNER 3½' N OF & E-W RD & 9' WEST OF FENCE LINE SOUTH.
RP'S SPIKE IN E SIDE PP# 43340 SSE 32.22
SE COR. CONC. BLOCK MILK HOUSE ON So. SIDE BARN NE 63.22