10-12-1963 set C/M near org stones #620705 (1)

section corner. west 7-18 Egota 106-12
east 12-13 Marion 106-13.

5-1883 Hunter P382 no 373 Lt. H Morse, etal

Corner gone, meas 40 chs south E 1/4 ℄ for line east
set ~~[illegible]~~ corner. unmarked stake.
1/16 north set stake 20 chs north. for line east.

12-1910 Chas Larson P142B L12. 8 parties.
found no corner - ground frozen. set stone.
everything 40 chs found very little, poor survey.

over)

10-1930 J Kerr. B4 P10

corner gone set stone 2x18x30 - cedar stake W side.
run line to W¼ 6. to help set corner for E-W (line)

Center 14" burr oak	S 24° E	12.8
40 D spike 14" " "	N 20° E	25.5

- actual data for placing corner, Meas W¼ 418 north to
℄ RR. 6257.2 + record ℄ 1632.18 (Hunter record from
℄ RR N to W 6-7) 7889.38 ⅓ 4 which 26298
and cont' line to Corner past at W¼ 6 for range line.
Too late to adjust corner now but W-6-7 at least 1640 or more.
from ℄ RR N. - all 4 sides ℄ corner common land for ½ mile.
so changing corner ℄ no significance at all.
4-13-81 found CIM in circle of limestone in trunk N-S tree
line. Kerr's 1930 witness trees still in place.

#620705 (2)

West 7-18 Eyota 106-12

Section corner

East 12-13 Marion 106-13

G ov. Notes 1853 Oct. Ball, Dep. Sur.
North betweeh 13 and 18.
80.00 Set corner post.
B r. Oak 10 in. S88W 19 lks. B r. Oak 14 in. N38W 176 lks. (116.16) (11.74)
Br. Oak 10 in. S10E 54 lks . Br. Oak 12 in. N75E 144 lks. (35.64)
(15.04)

8-30-82, West 7-18: Dug from a point 3' South and 1' West of Kerr's CIM, South for 6' and West for 3'. Found possible stake hole down 14", hole 3" diameter and ran down 8". Mark not pointed but ground very hard and bedrock 3" below
RP's to mark } Spike in small oak NW 6.38
} Spike in small oak SW 6.13
The mark appx 7.2 South and 2.2 West (d=7.74) Hard

nothing to determine direction. Measured 117' to 120' South from Kent's CIM to the fence West (very crooked tree to tree) which Hunter recorded 1.70 ch. South. We chained South (very roughly) appx 1314 and found small limestone standing under N-S fence.