X 5-11-72 set ½" x 36" rod by record meas. #621006
X 4-30-74 CIM set by M.H.D. crew over above ½" rod

¼ corner 9-10 Eyota 10 6-12 (1)

Jr Hurlbert.

10-1872 Hunter P 209 no 217, S10, N Coe, M Bowler.
found hole filled with surface dirt rammed with burr
oak bark, covered by Mr Wood as near to where
¼ post stood as he could gauge. until a year or so ago.
lines with old fence running east. this would bring the
¼ corner near 2 rods ~~east~~ of straight line between sec
corners - drove new stake as corner
— 1/16 south set stake M & L 20.00. to stake & rod
in line old fence running west as sec cor. N 35° E
Bearing 1/16 line east S 89° 55' E (over)

1/16 corner south to ℄ RR 9.58 632.28.
then " to sec cor 10.42. 687.72

Hunters record compiled acto RR references.
from ℄ RR south to ℄ E 9 10.92. believe used to 10.42.
actual meas ℄ to stone found. close to 690'
now have C/M's both N. & S. authentic stones

5-11-72 set 1/2" x 36" rod by meas. computed from records.
2641.3 N to C/M at 3-4-9-10
2638.65 S to C/M at 9-10-15-16
2604.8 E to cross in pavement at center 10. then
2646.16 E to iron at 1/4 10-11
43.13 W to head RR spike in power pole. (43.22 5-1983
48.15 S to ℄ crack in highway 14.
91.8 NNE to center 12" elm.
32.7 NE to center 12" pine.
16.0 W to center township road running north.

(2)

#6210006

1/4 Corner 9-10 Eyota 106-12

Set by William Jones 9-1853

40.00 Set post at qr sec corner deposited handful white flint. Made mound trench & pits, planted cherry seeds SW & NE.

6-23-83, 1/4 Cor. 9-10: Mn/Dot worked in intersection but found CIM in place, down 1'+, ___ E. of ℄ road North.

RP's: RR spike in South side pp. West 43.23

Punch hole in top N. end driveway culvert NNE 41.69

CSD in South side cut off pole NE 18.90
with telephone boy