8-1-73 set CIM over CIM after dug goods over (1)
#62205
5-17-1965 set CIM over iron rod.
Winter 1975 CIM. Leaning to South 7-75 Reset CJ M.
section corner. 11-12-13-14 Eyota 106-12.
6-1875 Hunter P281 no 278 & 12 dr & Zeb, John Bush etal
found remains old stake in center road, in line old fence.
set stone into place 3x8x14
1/16 north set stake with stones on N & S sides M & L 1321.65' 20.02 1/2.

9-1891 Thos Fraser P454 no 438 & 14. Charles Alden.
corner gone in road building, reset corner with boulder
8x8x16. by projecting line from stake at 1/4 cor north over 1/16
cor as placed by Hunter P281. Meas. 19.99 3/4 each.
— meas west 39.90 1/2 to stone set M & L. N 89° 40' W
(over)

5-17-1965 J Kerr B 90 P 13 L. Larson. staked acreage.
found stone exact size 8 x 8 x 16. 495' S x 1452 W.
set C I N over iron rod.
Disc tele pole gone.
" " " ~~W S W 125.0~~ "
~~S E 38.6~~

Meas west to 1/4 cor set as best as possible etc
2630.78. - recorded 2633.73 land level. ?

3-31-71 Co surv. found road graded high and about 100' R/W.
all RPS gone, all fences moved out to wide R/W.
- got very slight needle dip 75 or less about line fence north and very near south edge traveled road. 3 feet ±, ground frozen from 6" deep. Corner will keep.
- 5-65 JK showed be prop corner S 495.0 and 1452' W.
3-24-72 Co surv found small pipe near - Meas N- See 1/4 11-12.

June, 1867 H.E. Horton Pg. 86 No 132 Shows ~~1/4~~ Sec. Cor.
See survey for interior of Sec. 11

#621205 (2)

Card # 2. 11-12-13-14 Eyota 106-12.

dug grade cover out with tractor, found CIM top down 2'± placed anchor CIM on top - rod & CIM below left as is, Corner 3'± N of edge of road south edge.

33.75 ~~31.64~~ due S to 16D top center 9" cedar fence post past corner.

40.32. 10' E of N to punch hole top center W end 15" field culv

53.03 NE to " E " 42" road Culv.

129.78 ~~E~~ N SW to punch hole top center S end

1-15-75 found CIM tilted south. drove RR spike .4' N from this see NW corner RR spike

7-11-1975 dug along side of IM & set it up straight over Lower CIM

7-17-75

1/16 N. Found fence in 1/16th area now gone. Measured north recorded 1321+ from 11-12-13-14 and dug on line to fence post E of huge Willow at 1/4 Cor 11-12. Dug 2'x4' and probed but found nothing.

Set by William Jones 9-1853

(51.50)! Brook 10 lks wide runs East & Enter dry bottom.

65.00 Leave bottom

80.00 Set post at corner to sect. 11, 12, 13 & 14 deposited charred stake made mound trench & pits planted Br. Oak acorns N, E, & SW plum seeds SE & NW

#621205 (3)

SECTION CORNER 11-12-13-14 EYOTA 106-12

11-21-97 FOUND CIM WITH HEAD BROKEN OFF DOWN 0.5' IN CRUSHED ROCK TWP ROAD. ℄ TWP ROAD N 7½'.

1-9-98
EPA - TD
57

"621205" F

✓ SEC COR 11-12-13-14 EYOTA 106-12
FOUND CIM HEAD BROKEN OFF DOWN 0.3'
CHECK R. BRAND TIES TO PUNCH HOLES IN 15"
CMP TO NE. EAST END IS NOW ROLLED OVER A
LITTLE.

	1976+	1998
PUNCH HOLE W END 15" CMP NNE	40.32	40.37
PUNCH HOLE E END 15" CMP NE	53.03	52.99

CIM FALLS 8' S OF ℄ E-W TWP ROAD
+ 26½' W OF ℄ FIELD DR. NORTH. AND
9' E FENCE LINE SOUTH + IN LINE OF
FENCE ROW NORTH.