X 8-31-73 set CIM over stone rod 3 cards (1)
Cor 3-7-75 #621705
Section corner 17-18-19-20 - Eyota 106-12.

5-1882 Hunter P377 No 368 L 20 John Hughes, E Cornwell etal found LWBT standing and stump & LEBT. when found hole lined with old bark & surface soil where old stake had been pulled. set stone, quarry, 22" x 8" x 4" tapered.
-1/16 east set stake M & L 19.92 1/2 L 89 1/2° E
6" Oak N 66° W 123 1/2 lks
15" Willow N 61° E 59 lks
witness stake south 33 lks
-1/16 south. set temp stake M & L 19.97 1/2.
-1/16 center NW 1/4 20 set marked stake inters lines.

6-1883 Hunter P384 No 375 L 19 John Hughes over)

found stone center road. P377.
Meas west to 1/4 18-19 40.05' set by meas. prop.
Then 38.75

6-1893 JT Fraser P512 no 480 L18 JWilson, JCampbell.
found stone placed by Hunter P377 & SW BT.
left as found.
1/16 north set limestone M & L. 19.91 3/4 (1314.55'
-meas west 39.96 3/4 to stone set M & L.
no apparent prop meas for west part of township

10-1930 JKerr L18. B4 P10
found stone. 2629.5 north to E 1/4 18 as found.

8-8-68 JKerr, Joe, Pat. Meas from rod at 16-17-20-21
as O.C. 1/16 corner on bridge, set rod at SW17 at 5257 R5258.8
-Tel pole LE 50.6 — power pole NE 44.2

#621705 (2)

Details Card # 2. 17-18-19-20 Eyota 106 12

B4 P10 Dec 18.

10-13-1930 J Kerr dug and found above corner. ran line west found S¼18 at 2639.2., Cent line found SW18 at 5192.36. or 2553.16. set B tree.

10-14-30 ran north from above corner SE18 – set tube at 1314.55 and 2627.7 – found E¼18 at 2629.5 at 13.8 W of random. Cent line north found NE18 at 5254.0 from 2627.7 which was actual true meas of S½ of line. R. 39.83½ M&L – 2629.11

– did not search for ⅛ limestone set by W Fraser M&L 19.91¾ (1314.55

Reference Book # 4 P 26 as SE18 "stone 8" at bottom 4" at top 22" long found 10-13-1930.

8-7-1968 J Kerr. Meas from rod set as .00 at SE17 now moved 2.35' east, set rod in line center road north on apprx ℄ road east at 5257. or 5259.35 R. 5258.8 (corner supposed to have been destroyed by placing culvert.

RPs telepole SE. 50.6 – power pole NE 44.2

4-23 & 26-1971 Co Surv. ran & meas line betw 17 & 18. set lath 300'± north of rod on random. shot to ℄ road. about 800' south of C/M at NE 18. line proved near an exact parallel missing NE 18 east 3.5' and center stone found as 1/4 17-18 east 3.6', ~~but~~ at 2623.55 R.W.F 2629.1 J Kerr 2627.3. - but 1/16 stone south of 1/4 17-18 came only 2.9' from line (stone long way E & W, may have taken W corner) should have been 3.6'. Set 1"x5' pipe at 1/16 S of stone entering over stone at surface. piece of conc lying west of pipe R. Pt on 1/4 17-18. - set 5/8"x2' rod as section corner by exact line from 1/4 17-18 over 1/16 stone making kink at 1/4 corner stone .75' west of direct line - Corrected points north of 1/16 at 585.25 and 1081. S of 1/4 stone to 1/16 set. Rods 33' west of true section line.
- will dig with tractor for section corner stone, altho claimed taken out by road culvert. present corner location corner 5259.8 west of rod Set as 16-17-20-21.

See card 3.

#621705

Card # 2. 17-18-19-20 Eyota 106-12 (3)

8-31-73 RP changed

RP to rod as set 4-26-71 new. 38.07

punch hole in west end small culv of road N. NW ~~37.05~~

punch " east new 18" " NE 38.45 ~~37.56~~

Disc (county) in power pole # 15764 (plumb 18" above disc) NE 49.23 ~~49.27~~

Coke cap on NE side tele pole (2 overhead wires) SE 43.5

exact line center power poles running south E 39.2

CIM should be set at this point if no corner stone found below.

4-26-71 Meas west from 5/8" rod as set on transit line from hard nail set in center present blacktop road in line fence North and fence ridge south.

set P.O.T. hard nail at 1242.26

found nail at 1/4 18-19 at 2638.06 R Hunter 2643.3 1883

Will Fraser R. 2637.85 1893 J Kerr 1930 2639.2

8-31-73 found iron pin set 4-26-71 on exact line and double distance from 1/4 17-18 over 1/16 slope south.
1313.17 R. W Fraser 6-1893 P 512 1314.55
- true to John Kerr information a massive 8" wall box concrete culvert 4' square with top broken in down 5' or so to bottom sluice. Mr Jones of section 19 said he saw junction still in place in huge washout in that area when box culvert made.
See changes in R P S. set 4-26-71 set C/M over rod. exactly where rod found. corner spiral no mark exactly east

#621705 (4)

Section Corner 17-18-19-20 Eyota 106-12

Set by William Jones 9-1853

80.00 Set post at corner to sect. 17, 18, 19 & 20

Br. Oak 12 N 36E 150

Br. Oak 10 N 43W 128

Br. Oak 4 S 29W 88

Br. Oak 4 S 41E 89

1992: Line from SE 19 over E¼ Cor 19 comes 2.8 West of CIM here. Line from NE 18 over E¼ 18 would come 1.2 W