X 4-26-1971 found stone and iron bar. #621706 (1)

1/4 corner 17-18 Eyota 106-12. 2.

6-1893 W Fraser P512 No 480 L18 J. Wilson, J. Campbell.

corner gone, no evidence or knowledge of corner.

set limestone with stake by stake N & L 39.83½ (2629.1

-16 south set limestone N & L. 19.91¾ (1314.55'

-drover stakes 80 rods 1320' south of NE cor 18 and another stake 35 rods 577.5' south of above stake.

10-14-1930 J Kerr B.4-30-2 P12. Mut Benefit Life Ins Co Newark L18.

found SE cor 18, ran & meas line north. set hubs at 1314.55 and 2629.1 ~~2629.7~~ found ~~set~~ limestone and stake at ~~2627.7~~ 13.8 W of random

- no reference, did not search for 1/16 stone.

- cnt line north. found W Fraser iron at NE cor 18 at 5254.0'

(over

line from 1/4 17-18 north 215.0 level, then 130' at 9°L 128.38
then level 235.0 (578.38) then 130' at 36°20'L 104.73 (583.11) (343.38)
then 21' (704.11) then 300' at 1°40L - 299.88 (1003.99) then 800' level
(1803.99) then 500.00 level (2303.99) then 292.0 and 31.65
Total 1/2 mile from 1/4 corner 2627.54 or 5255.34
Midway would be 2627.57

4-23 & 26-1971 Co surv ran & meas line from NE 18 C/M at corner. started random to see near enters mile, came 3.5' east of C/M at NE 18. and 3.6' east of center stone found at 1/4 17-18. at 2623.55 with part of line triangulated into valley. accounting for J Kerr meas of 2627.3 being longer. - found 1/16 stone 1313.77 south of 1/4 17-08 stone double 2627.54
J Kerr 2627.7 2nd F 2629.1 all for S 1/2 of line.
- N 1/2. 2nd F 2629.1 J Kerr. 2627.3 1971 - 2623.55
1/16 stone fell .75' east of direct line from C/M over center 1/4 stone so projected line of 2 stones to replace S E 18. See Card No 2

1/4 corner 17-18 Eyota 106-12 Card #2. #621706 (2)
set steel fence post on East side stone found at 1/4 17-18
a 5"x10" top limestone at least 24" long with top flush with
surface. and a pointed 1" drive axle shaft 2' long on west side
RPs 1/4 17-18. Blazed 16" bur oak. 5' W of N 15.2.
Center Blazed 22" " " 8' W of S 21.3
corner slightly north of main line of fence running west
and 20' west to large new corner post. W edge Old road.

---

at 1/16 south found 2"x7" top long limestone 4½' down
which came 5" west of west edge of traveled road surface.
set 1" x 5' iron pipe north of stone centering over stone at
surface driven down to. put ½ cone building block over pipe 2' deep
RP 1/16 20 D on. NE side 20" bur oak up 1' NW. 92.3
20 D on. NW " 18" " " up 1' on fenceline NE. 77.92.
No 8 on no plate 15862 A power pole SE 83.53
Corner

ac. line at NE18 fell 3.5 east of CIM, and 3.6' east at 1/4 stone and 2.9' east at 1/16 stone a kink developed at 1/4 corner. If new line from 1/4 stone over 1/16 stone proj. south it fell only .47' west of rod set in 1968. set at 5257.0 from rod set random at SE 17 R 5258.8 (00 rod later moved 2.35' east of conform with lines north at 5259.35'
- If line proj NE 18 over 1/4 stone SE18 would fall 2' east of rod.
- set 5/8" X 18" rod as SE18 on line ~~of~~ 1/4 stone and 1/16 stone with doubling distance. see RPS. on corner card.

Set by William Jones 9-1853
40.00 Set post at qr section corner
Br. Oak 7N 89½E 48
Br. Oak 7N 87W 45
44.70 Stream 12 lks wide runs S.W.

#621706 ③

1/4 Corner 17-18 Eyota 106-18

8-5-1981 1/4 Cor 18-17: Dug out 6"x10"x20" stone and drove
telepar with cap. Set stone on West side of monument.
Put survey marker sign and post in E-W fence
line 3' South of the monument. Corner is ±21'
East of fence South.
RP's: Spike and CSD in 18" B.O. NNW 15.07
Spike and CSD in B.O. ENE 67.20