9-18-95 CHD SET 1" SQ PIPE W/CAP.

#622004 (1)

1/4 corner 20-29 Eyota 106-12.

5-1882 Hunter P 377 No 368 S20 John Hughes, E Cornwell. found stone in center road - tested OK by N-W B Tree. -1/16 west set stone 2 x 10 x 19. M & L 19.96 pointed on top used for line north

this 1/4 used. to set sec corner SW 20 west midway to S 1/4 19.

also used " " " " east S E 21 P [redacted].493.

or the SW cor 20 used in P 600. to set S E 21.

7-1892 Thos Fraser P 493 No 467 S 21. Dugan, Ferry & others found recorded stone. used to set S W cor 21.

- produced line from S W cor 20 over stone at S 1/4 20 to set S W cor 21. Hunter however in 1896 P 600

OVER

Could not find stone and mean S E 21 to S W 20 ignoring his own corner at S 1/4 20.

T Fraser mean S 1/4 20 east 1/2 miles 3 x 39.87 (2631.42'
Hunter P600 mean 2 miles S W 20 to S E 21. 159.44
1/2 of which 79.72 and found stake 79.71 from S E 21.
(5261.52) (5260.86)

Set By William Jones 9-1853
10.35 Bur Oak 6 in. diam.
39.95 set post at qr. sec. Corner
Br. Oak 8 S 42 E 103
" " 7 N 44 W 34

stone 2 W 8.75
N 9.37

6-13-78 Dug with backhoe on line from nail set from tree at S.E. 20 to CIM @ S.W 20. Dug
1st dig [illegal] 31' [illegal] e. Covered Hunter measure from
2nd dig 8½ SW 20 and T. Fraser measure from SE 20
and the fence line North. The old road has run
into clay. Found nothing.

1/4 Corner 20-29 Eyota 106-12 (2)
#622004

7-20-78 Dug with backhoe South of ℄ to cover location of T. Fraser corner on line from SW 21 to the SE 21 set by him farther South of Hunter SE 21. Found stone (4X12X15) boulder ± 6' South of ℄ Co. Rd. #23 flush with surface of old road. Took pictures 16-18 on mini-camera, set iron along side of stone with junk around.

7-24-78 Set ½" X 20" iron at road surface on stone.

RP.s: CSD NW side pp. (no #) SW 76.58
CSD So. side pp #1564L NW 106.93
spike W side 14" Burr Oak in Fe. N N.69.60

6-13-78 (1/16th West) dug on line and at Hunter's measure from S.W. 20 (which came 6' West of fence So. Dug  line by 4½' deep. Found large cement slab- poured at corner location (probably to cover fort boil). Found nothing.)

After finding ¼ Cr 19-20 South of this line the corner also would be So. of line but Cement slab- makes condition very poor.

1/4 CORNER 20-29 EYOTA 106-12 (3)

#622004

6-19-95 — FOUND 5/8" IRON ±6' SOUTH & CR #23. SET 1" SQ PIPE W/CAP SSW OF CORNER AS TIE. & CR #23 NORTH 55'1/2'.
T @ REF PIPE
3RT TOP CENTER WHITE TOP SILO ENE TO 1/4 COR 20-29
280° 37' 43.5"
TO 1/4 COR 20-29 (5/8" IRON)
VA 87° 21' 48" dv 07
SLOPE 50.12 HOR 50.07

8-23-95 - SET P.K. NAIL @ REF LOCATION FROM 6-19-95 IN NEW BLACKTOP CR #23

9-18-95 - CHD SET 1" SQ PIPE W/CAP.