#622206

1 8-31-73 Set C/M directly on huge recorded boulder found 3-7-75 (1)

¼ corner 21-22 Eyota 106-12.

7-1892 Thos Fraser P 494 No 767 L 21 Dagan, Fury, etal
cond'n find corner relocated M & L 39.99
-1/10 west set limestone M & L 19.93½ (1315.71'

11-1856 Hunter P 18 No 29 L 22
used corner set 1/16 east 19.81½ M & L. 1307.8
to center 22 then east M & L 19.79½ 1306.97

5-1896 Hunter P 599 No 544 L 22 Haggerty, Bazzian.
corner completely gone. set boulder
8 x 22 x 30 M & L. - Meas north 39.99
Meas south 39.99. N½°W.

8-8-68 J Kerr Joe-Pat.
used Tie rod set at 15-16-21-22. meas south from ℄ E-W road.
5.0' south of rod - set nail at 2640 R 2639.33 in exact line
fence east. in center road. - 31.4 east to bird hole in Cor F post.
- suggest recorded stone P 599 could be found at that spot.
- 8-11-69. John & Pat. found center 21 perfect Meas east R 2631.4.
set 40 D at 1315 some 18" south of E-W fence. ground sandy & super dry.
could hardly bank found nothing in area dug. - station of fence north
1340.4 no fence south - cont meas east set nail in direct road
ditch at 2615. ℄ road near 2633+ - will probe for 1/16 later.

5-11-1970 C surv. tried to find 1/16 corner west. - dug & probed entire
area. run 15° ⊙ line N at Center 21 and fence east at 1/4 21-22 & meas
entire line. set iron pod with cast iron cap on top on 1/16 with 1 1/2 bolt by side
of Yellow pine - a temp corner subject to change - 1' south of E-W fence
and 26' E N E to corner fence post
- cont line east, set 1/2" rod at 2631.4 in line fence east. subject
to digging for stone. - corner 3' W center road
- 16 D set top new post anchoring new fence east 6' east of old cor post E 41.3

Card # 2 1/4 21-22 Eyota 106-12. #6222206 (2)

8-31-73 found 1/2" rod set 5-1970 on line and measure from Center 21 R 1315.71 M & L set 2631.4 E of Center 21 C'1 M.

dug with backhoe found huge 8 x 22 x 30 boulder. a reset 1/4 corner in 5-1896 by Hunter.

- stone about 2.25 E of rod near N-S line. Stone so huge and no hole or cross it anypoint ± any direction set C 1 M directly on stone center.

39.05 E to nail on top Cedar brace post 1971 41.3.

36.25 S E to nail in wood brace type post.

Meas north (no check 1973) but very close to 2640'

over

1/16 west. see Card #1. showed now mere east 1/2 of
difference stone found east of rock or about 1.12' east
to be midway. entire area there dug, very hard when
dry and of course being 7' S of E-W fence stone
long gone as 1/16 fence. Iron 25'± east of 1/16 set it
could be noted that on N side of NE 1/4 21. the 1/16 fence &
actual corrected would fall about 1' east of midway betw.
NE 21 and N 1/4 21. R 1318.35 M & L now actual 2638.0±
so. fence OK on N side and natural "pot-hole" make
line go west considerable.
- fouldersrecorded at 1/4 east of 1/4 16-21 almost sure to
be in place but did not dig for it.

#622206 (3)

1/4 Corner 21-22 Eyota 106-12
Set by William Jones 9-1853
30.69 Br. Oak 9 in. diam.
40.00 Set post at gr. Sec. Corner
Red Oak 6 N 74 E 45
Burr Oak 6 S 46 W 1040