10-16-75 Set C.I.M. 10-31-95 CHD SET 1" SQ PIPE W/CAP

¼ Cor 25-36 Eyota 106-12

#622504

10-6-75 Dug 8'x8'x5' deep from ℄ E-W road N at M&L location but found nothing.

10-16-75 Remeasured the N. line Sec. 36 after setting C.I.M's at the NE and NW corners. Reset the corner M&L at 2641.175. Set C.I.M. over ½" x 18" iron rod. Corner lies 3.5' N. of ℄ of E-W C.R. 129, 1'E of fence line S; and 1'E of fence line N.

RP's CSD N. side pp # 1743 NW 124.41

CSD E side Oak corner post N. 42.09

Punch hole in top Center N. end 30" conc. Culv. NE 68.57.

Punch hole in top center S. end 30" conc. culv. SE 72.09

Set by William Jones 9-1853

40.00 set post at qr sec corner deposited handful of gravel made mound trench & pits

---

6-19-95 - FOUND CIM, SET P.K. @ SURFACE. SET 1" SR PIPE W/CAP ± 40' SOUTH & CR #129 + 5' WEST OF FENCE LINE SOUTH.

T @ REF PIPE

ART OLD BLUE EYOTA WATER TANK TO 1/4 COR 25-36 28° 21' 17"

TO 1/4 COR 25-36

VA 84° 06' 31" dv 08 SLOPE 44.15 HOR 43.915

10-31-95 CHO SET 1" SR PIPE W/CAP