8-17-1965 C/M set by Co Hwy Dept. (1)
9-20-95 SET 1" SQ PIPE W/CAP CHD
10-3-75 CIM unfnd
1/4 Corner 26-35 E yoke 106-12 #622604
5-1902 W Fraser P14B & 26-27-34-35 5 parties see N 1/4 26.
found stone center road.
1/16 north set temp point 19.89 1/2 M&L for line west.
1/16 west set stone 19.91 M&L
1/16 center & W 1/4 26. set boulder 4x5x14. inters lines

Co Hwy Dept. 1965 B165 last page found limestone set C/M & RP Ld.
Disc fence post or telepole. NE 109.3 Cor fence post & 45.56.
" fence post NW 5.16.
" power pole & W 62.3 over 1/16 ties west.

1935 C.H.D. Book 53 Page 67 Found stone

1/16 west found stone iron bar on south side.

Sp pine LE 52.2

" 2nd fence post S. 39.8

" tele pole NW 92.7

10-3-75 Dug down to verify Co.H.D. C.I.M.. Found CIM over 3" x 9" x 12" limestone 2.4' deep with glass beneath in clay. Set scrap iron by stone and left CIM in place.

R.P's: Punch hole top E end CMP to field drive N N29.46

Punch hole top W end CMP to field drive N NW 38.38

Punch hole top E end CMP to field drive S S 31.26

Punch hole top W end CMP to field drive S SW 38.91

CSD N side pp # 1764 SW 62.36

CoHD disc in corner post NW 51.45

Corner in ℄ E-W road and 2' N of fence S

5-22-81 Co. Surv. found ℄ nail in new BlackTop: checked with Ties OK.

#622604 (2)

¼ Corner 26-35 Eyota 106-12

Set by William Jones 9-1853

40.00 set post at gr. section Corner

Br. Oak 7 N 17½ W 61

" " 8 S 16 W 63

April, 1863 P.C. Compton Pg 68 No. 96 shows ¼ Stake used to set Center Sec. 35 at intersecting lines

---

6-19-95 — FOUND CIM. SET P.K. @ SURFACE. SET 1" SA PIPE W/CAP 47' SOUTH OF ℄ CR #129 + 2' WEST OF FENCE LINE SOUTH.

OVER →

6-19-95 CON'T –

T @ REF PIPE

∠RT P.K. IN P.P. #1763 (1st POLE EAST ON S SIDE CR# 129) TO 1/4 COR

270° 03' 58.5"

TO 1/4 COR 26-35

VA 88° 27' 40" dv 04

SLOPE 48.215 HOR 48.195

9-20-95 CHD SET 1" SQ PIPE W/CAP