1 6-6-1973 dug entire area after re-running line. #1
found nothing, set nothing.

#622704

1/4 Corner 27-34 Cyota 106-12

11-21-34 Set a C.I.M. over rod

5-1902 W Fraser P14B & 26-27-34-35 5 partics see N 1/4 26

could not find corner - set stone 6x6x18,

M & L 39.89 N 89° 55' W 2632.74'

"6" 1/16 north set boulder stone 19.94 M & L. 1316.04

"3" 1/16 east set stone 2x6x17 M & L. 19.94½ 1316.37

"8" 1/16 center SE 1/4 set boulder stone at intersection.

No meas. Meas meas. N side SE 1/4 1316.37 M & L.

S " " 1316.37 M & L.

E " " 1315.05

W " " 1316.04

6-6-73 found recorded 1/16 stone in center township road in line fences N and S. about 2.5' deep to top. top of stone about 3"x7" recorded 2"x6" very vertical.
40.7 S to nail W side corner post of fence S.
50.8 SE to nail NE side PP# up 4'+
set square head bridge bolt. 3/4"x 24" riser overstone.
Meas from above 1/16 west to C/M over stone at.
27-28-33-34 9948.66. Making each 1/16 corner at 1316.22 from which 1/4 27-34 must be set.
- dug entire area with tractor and found nothing using line and meas as guide set nothing but small nails used in traverse, can easily reset.
Must re-run line 12-73

#622704 # 2

¼ corner 27-34 Eyota Twp. 106-12

8-27-79

Reran the South line sec 27 and set the
1/1 cor. at 1/3 of the West ¾ of a mile.
Using the S.W cor 27 + 4/16 E of the ¼ cor
Location for line. W½ - 2632.41 elec.
1/16 E. = 1316.20 + 1316.21 to S.E. corner 27.
Set a ½" x 8" ± at the cor.
11-21-74 Set C.I.M. over Rod

R.P.'s

| | | | |
|---|---|---|---|
| Nail N.E. side | cotton wood | S.S.E. | 55.43 |
| C.S.D. N.E. side | tele post (with box) | N.W. | 177.67' |

Corner falls 4' West of the cor post North + 6' North of ℄ E.-W. Co. Road.

Cover

Gov. **Notes** Oct. 17, 1853
West on true line between sections 27 and 34.
Var. 9° 47' E
39.82 Set post at gr. sec. corner.
Br. Oak 12 N 88 E 430
Br. Oak 5 S 89 E 370
79.64 To section corner

---

May, 1856 Thos Hunter Pg. 6 No. 10 Shows 1/4 Post
1/16 west 19.94½ m&L - 2 B.T.'s (N 54¼°W 194 lks.) & (S 3¼°W 70½ links)
meas. North 39.76 Chs. to Cen. Sec.

April, 1863 P.C. Compton Pg. 68 No. 96 Shows 1/4 stake Set M&L
between Sec. Corners. (See survey for story on problem
with witness trees, used 1/4 Corner to set Center 34
at Intersecting lines.