/ 7-27-78 Set CIC #622904 (1)

1/4 corner 29-32 Eyota 106-12.
11-1856 Hunter P17 no 28 & 29
used corner to set center 39.79 N 55° W.

5-1890 2hos Fraser P442 no 428 & 31 Weaver James Campion.
cored not find corner to use to set NE 31 - meas each
To N'4 33. & line 29 2633.15 set nothing.
N'4 33 found & used to N'4 31. Hunter's date illegible. 159.58½ 10532.61
7-1939 J Kerr P488B & 28-29-32-33 Town Board.
BK 15 P.125
cored find no trace of corner, in abandoned road.
meas SW 29 to N'4 33. - ~~S line~~ (SW 1/4 28) 29 - 2629.22 set nothing
Fraser says N'4 31 to NE 31 recorded as full meas. over.
according to Govt mees.

balance of meas to N¼ 33. short. each.

5273.40 5266.14

18.99 60.00 79.90 79.79

39.94¾ John 5265 − 10½ 39.89½ John 5251.52 − 5¼

2636.53 79.79½ 39.84¼

159.58½ actual 5266.47 2629.6

½ 2633.23

Sec 29 expect midway on south line to be. 2633.23 however.

Starr P 488 B15 P128. Meas Sec 29 to S¼ 28 2629.22 each and 2622.3 east to 27-28-33-34 making possibility that ¼ 28-33 not midway.

[redacted]

#G22904 (2)

¼ corner 29-32 Eyota 106-12
Gov. Notes Oct. 17, 1853
West on true line between sections 29 and 32
Var 9° 40' E
39.95 Set post at gr. sec. corner

79.90 To Section corner

7-24-78 Tried to dig for this corner with the backhoe but water kept filling the hole so couldn't get a good look. Dug from t.i.n. So 1', W 8', E 6', N 9'+, but found nothing.

7-27-78 Set a CIC on a 5' square pipe as the corner in line with the N-S fence and at double the measure from the stake found at the Center 32 in 1973 over the fence line West (this is approx since fence removed and only ridge

remains) at the 1/16th North. The corner is 2' N. of the ℄ of the old road E-W. Set a survey sign and post 1' West.

RP's: Spike in East side brace post SSE 20.04

Spike in West side c.p. S. 18.93

CSD in East side c.p. N. 14.18