X 6-4-1968 set C/N over orig stone. & (1)
iron pipe (plate)

1/4 corner west 1/4 30 Eyota 106-12 (#623006
east 1/4 25 Marion 106-13

6-1877 Hunter P 318 No 312 & 25 James Campion found original corner standing by fence, tested by B tree stumps and proven correct- set stone in place of stake. - Meas north 39.97 To stone set from stake remains.

3-1878 Hunter P 332 No 326 & 30 R.W accord & J Campion's found stone P 318 tested B tree stumps
- 1/16 east set stake at 18.80 1/2 then 19.93 1/2 to center S 89°5'E
this meas arrived at by proportion on meas of govt meas of north and south sides of W 1/2 30 - 38.75 south - 38.99 north
the govt mean is 13 lks short of actual measure. (ones)

1/16 north set stake or corner 19.97 N & L N ½° W.

11-1961 DaVal - Minn Hwy Dept.
flat stone in fence line - lines E-W-N-S fences.
corner lies 328.0 south of fence corner.

6-4-1968 J Kerr
found stone under N-S fence. just .6' ± Northwest of permanent highway marker.
corner really is about 320.0' south of random fence north as it runs west.
another highway ▽ marker lies 60' north.
set C/N on top of stone top slightly above ground.

#623006 (2)

West ¼ 30 Eyota 106-12
¼ corner East ¼ 25 Marion 106-13

Gov. Notes 1853 Oct. Ball, Dep. Sur.
North between 25 and 30.
27.21 Br. Oak 10 in.
40.00 Set quarter post.
Br. Oak 10 in. N87W 39 lks.
Br. Oak 12 in, S81E 62 lks.
1935 MHD used corner post (book 87)