X 6-30-69 set CIM on log corner wedged under pavement
section Corner. township Corner. SW 31 Eyota 106-12. ①
NE¹ Pleasant Grove. 105-13 - SE 36 Marion 106-13 #6023105
NW 6 Orion 105-12.

7-1876 Hunter P302 no 297 26 N neal.
found stake center road a'ered by John Campion as true
corner at site of orig corner. - no meas or bearings

5-1890 Thos Fraser P442 no 428 31 W a'ers James Campion
found engraved township corner set by Hunter.
- meas north 39.98 3/4 to stone set M & L. N 40' W
- line east deflects south near 1½ rods to ¼ 31 (over earlier survey)

7-1876 Hunter P 301 No 296 & 1 N Neal ——
found stake center road covered by John Campion as
site of orig corner.

5-1880 John Fraser P 365 No 356 & 1 Pedmore,
found monument set by Hunter

6-1903 Armstrong P 63B & 1 NW 1/4 1 Thomas Donaldson.
stones set at N 1/4 1 etc.

Co Hwy Dept B 88 flat limestone oak stake on top
cor F Post NE- 31.9 — Cor F P NW 40.4 — Cottonwood SW 75.5

State Highway 52
Corner lies 7' north at Station 455+86 line fence N.

see card No 2.

#623105 (2)

Card No 2. township corner. SW 31 Eyota
NE cor 1 Pleas Grove. NW cor 6 Orion SE cor 36 Marion
6-30-69 J Kerr. Meas & run line from NW cor 1 Pleas
Grove east. also run & meas line from NE 36 Marion
over E 1/4 36 Marion both C/Ms over org stones.
from brass plug .15 from north edge pavement. only .15'
east of line shot from mile north aerial
- meas NE 36 south To E 1/4 36 Marion 2636.7 R2639.2
- meas E 1/4 36 south To brass plug. 2636.65 R2639.2.
found square stone centered below brass plug 20" below
bottom pavement wedged C/M between stone & bottom pavement
- meas west To S 1/4 36 set 2638.9. a cross cut in pavement
over -

from S¼ 36 west to SW 36 — 2636.3

– meas south to E-W fence at ¼ corner 2633.45

set C/M at SE cor / using 2633.45 as midway.

R 40 chains set as midway on early poor survey.

RP twig cor. state mon sta 449+26.4 at fence south.

on south RW – west 659.6 R 659.6

– state station & twig corner 455 + 86.0 (no mon).

– Cole cap on S side Powerpole #16451 3' up ENE 102.9.

put glass etc around mon.

– triangle RW post denoting south RW (new) SW 105.8

– " " " " north " " NW 96.0

1938 B96 P4 CHD. found brass plug on ridge pavement. did not dig up corner. 9.9' W of E hotel say 7' N. used plug. Meas west 2637.5 mark in line fence south.

#623105 (3)

Section corner, township corner. SW 31 Eyota 106-12
NE Section Corner Pleasant Grove 105-13 SE 36 Marion 106-13

NW 6 Orion 105-12

Gov. Notes Ball, Dep. Sur.
North between 1 and 6.
80.00 Set post and drove charred stake.

"623105" SW COR 31 106-12 TWP COR
FOUND BRASS PLUG IN CONC TH 52 UNDER
4" OF BLACKTOP IN GOOD CONDITION.
CORNER FALLS 9.4' N OF ℄ TH 52 + 188' W
OF ℄ FIELD OR N.
BOTTLE CAP IN PP# 16451 NE 102.52
SET 1" SQ PIPE/CAP ON S R/W OF TH 52
52' S OF ℄ TH 52 + 205' W OF ℄ FIELD OR S.
DOWN 0.6'

4-8-91
LPA JPJ - BB

"623105" CON'T
T/@ REF PIPE
& RT JJS TO "623105"

264° 21' 29" dh 01	266° 55' 20" dh 04
0° 08' 05" dh 00	2° 41' 55" dh 00
264° 13' 24"	264° 13' 25"

TO JJS
VA 91° 05' 50" dv 02
SLOPE 189.115 HOR 189.08

TO 623105 (BRASS PLUG IN CONC.)
VA 90° 11' 43" dv 02
SLOPE 62.105 HOR 62.10