X 7-1-1968 set C/M over reg stone & 3/4"x10" pipe

section corner south 31-32 Eyota 106-12 (1)
north 5-6 Orion 105-12 2

#623205

7-1876 Hunter P302 no 297 S6 N Neal.

Corner gone - John Campion aneres he set fence posts equal distances from corner. split these posts and used as corner, set no permanent corner.
- meas south 38.01 to 1/4 cor set by prop meas.

5-1890 Thos Fraser P442 no 428 S31 2nd weaner James Campion.

Corner gone found post remains described above anered by John Campion. Looked extensively for SE 32, 1 mile east 3' deep across road. so set stone 3x12x24 between posts on opposite sides road as dictated by Campion owner of lands on both sides. (over)

-Meas north 39.92 9/16 to 1/4 cor set M & L on 2 mile line S27'W
-1/16 west set stone 2x18x?0 M & L. 19.96 1/4 S89½°W
1317.52.

State Minn Hwy 52 notes
Corner lies 17' north P.O.S.T. ~~center line pavement~~
at Station 507+96.5 in curve.
station PC 506+21.4

7-1-1968 J Kerr to relocate corner.
run and meas mile from NE corner 31 south.
found recorded stone at corner. - set 3/4"x10" pipe over stone below E/M. - top mon down 8" (over)
this data S 31-32 Eyota N 5-6 Orion

Card #2 S 31-32 Eyota 106-12. (2)
N 5-6 Orion 105-12
#623205

Meas from C/M set S 31-32 N to ¼ 31-32 2634.95
Meas from C/M at ¼ 31-32 N to 29-30-31-32 2635.4
Meas west to ⅛ fence running North 1317.8 near record 1317.52
– Corner lies in center roads north and south.
– Corner lies 28.03 south to ℄ conc par on proj ± S.
– RW Marker post NE 36.3.
" " " NW 40.45
52 sign marker post W 59.8
– orange cap in power P #16470 NW 46.45.

4-1-79 Set 10" CIM on Kerr C.I.M (top section broken off) Corner in ℄ road N.

probably will be moved 5/14/79

R.P.s CSD NE side of pp # NE 46.46

CSD S. side of corner post NE ~~34.90~~ gone 5/14/79

P.K. in ℄ Hwy 52 S.28.18

NO GOV. NOTES ON THIS CORNER

5-14-1979 Retied CIM for road grading.

R.P.s: Punch hole top West End CMP in road South SW 70.52

P.K. in ℄ T.H. 52 and ℄ rd. So. South 28.19

Punch mark East end C.M.P. in road South SE 75.51

"623205"e S SEC COR 31-32 EYOTA 4-5-99 EPA BB

FOUND KERR'S BROKEN CIM DOWN 13" (6" BLACKTOP) IN ℄ CSAH #19 NORTH + 28' NORTH OF ℄ TH 52 NOT @ RT ⅄.

CHECKED TIES FROM 1977. 4-8-99 EPA JPJ BB

CSO IN NE SIDE PP# NW 46.37 (46.46)

PUNCH HOLE IN E END CMP SSE 75.41 (75.91)

NO. 447

"bZ3205" S SEC COR 31-32 106-12
SET 1" SA PIPE W/CAP @ SURFACE OVER
KERR'S CIM

4-12-99
EPA BB