~~R&R~~

#623606

1

1/4 Corner 35-36 Eyota 106-12.

10-1-1973 Corner required for prospective survey. dug enormous hole in center road & road north abandoned. at least 10'x12' road gone, land slopes some 500' both from East and west. so old road must have been very low and washed away.
- section line south once old road running along line to Orion town line when it follows fence entire line south of 1/4 35-36 super rough and massive brush and trees never a pasture line corner lost - & 35-36 lost. road east crooked also.

over

10-8-1975 Co. Surv.
dug again with Tractor - dug hole about 6' N-S x 8' E-W 5' deep.
Using 33' East of road fence North on W. side of old road as The West end of our digging and just ± 2' N. of ℄ as center of N-S digging. - did not find anything.

10-10-75 Dug 9/4 x 18 x 5 deep to bedrock but found nothing. Used line from 1/16 W of Center 35 over Center 35 for N-S. Covered area of intersection of this line with theoretical section line and also area 33' E of N-S. fence on same line. Digging came in S. 1/2 of road.

April, 1863 P.C. Compton Pg. 68 No. 96 shows 1/4 Stake used to set Center 35 at intersecting Lines. (Reset from witness Trees

#623606 2

¼ Cor. 35-36 Eyota 106-12

Gov. Notes Oct. 17, 1853
North between sections 35-36
Var. 9° 55' E
39.00 Enter 1 st rate prairie E and W
40.00 Set post at gr. section a9
Br. Oak 14 N 66 E 227
Br. Oak 6 S 47½ W 340

4-28-81 (GW) Set a CIM over a 5/8" rod on the line from the West ¼ Cor 35 over the Center 35 and in line with the road North (S ¼ 3rd off). The corner came 7' South ℄ of E-W road and 27' East of the fence North on the West side of the road. RP's & CSD in West side fence post (end of fence N NW 63.00 CSD in NW side corner post to fence West Cor South side of road) and South. SW?

8-5-85 Fd CIM DC Corner 5' E of new Shorafelter Fc. So.