#630106 (1)

6/12/67 set CIC/P²

1/4 corner 1-2 Marion 106-13.

no records. Lee (over) to Hunter unrecorded survey.

Mc Ghie survey in 2. - set 1" pipe in stones 5/8" iron made pipe

Sp in 30" twin elm LW 34.0

Sp in 15" fr oak. NNE ~~ESE~~ 32.0

Kerr 1962

B 85 P 74. run line west to center sec 2 - 2627.5 set rod at 1/16 cor M+L which came in N-S 1/16 fence which is a rather rough brushy irregular fence line.

Gov't Notes: Oct. 1853 W = A. Jones.
40 ch. Then 40.20 To N. Sec. Cor. 1-2

B.T.1 Br. oak 10" North 172 lks 113.52
B.T.2 Br. oak 6" N 25° E 29 lks 58.74

166.87
172.375

8-23-73 found unrecorded survey in book [3] between surveys # 151 and # 152 for Mulberhill 6-1873 W 1/4 1. " at D. found old original 1/4 post standing by side of fence post, tested it by stamp & the N ~~X~~ B T. tested fence post to be correct.
set points east to stone found at Center 1.
20.18. (1331.88) then 10.09 (665.94.) to property corner set as purpose of survey then 10.09 (665.94 to Center sec 1. set by Fraser. (Likely John Fraser.)
2663.76
N side ~~of~~ W 1/4. 20.07 1324.62 662.31 to prop cor then 662.31 or. 2649.24 to NW sec 1.

#630106 (2)

1/4 Corner 1-2 Marion 106-13

6-3-1982, 1/4 Cor 1-2: Found pipe with 5/8" re-bar inside on the East side of a 4" thick pointed limestone (15"/16") (up 7"). Both McSkimin bearing trees in place but bearings hard to check without compass.

6-21-1982, 1/4 Cor 1-2: Dug for "old Fd. Post" used as R.P. by Connie in 1958 and described as SW. 16.0 (spike in) from 5/8" rod set. Dug on 16' arc from rod and finally found the remains of the old post, rusty wire, and staples extending down 3' and in appx 14' South and 7' West of the 5/8" rod.

6-23-1982, 1/4 Cor 1-2: Dug North from fence post Fd 6-21-1982. Found another post hole 6.0 North and .5 West. There were piece of limestone standing on the SW side of the hole and near the ground

X's should be turned to these!

surface. There were several bits of wire. ~~The wire was cut~~ We dug from this post North for 9' but did not find another post or any more wire.

7-1-1982, 1/4 Cor 1-2: Dug from N'ly post found 6-23-82 (to try to prove it was Hunter's fence corner) for 9' East, 7½' West, and 11' North (2' more on old dig) but we could find no more post or wire.

1/4 COR 1-2 6/18/87 FD IRON IN PLACE & TREE NAIL ON HILL E'LY (1982) CHECKED FOR B.T.'S THERE IS A 30" OAK THAT WOULD PUT CORNER APPROX. 20' W & 2' SO. (BY COMPASS ONLY) OF THE IRON. DUG ON ARC (58.7') OF GOV'T TIE, CENTERED ON GOV'T BR6. (N 25°E) FOR APPROX. 4' N'LY & S'LY OF PT, SET UP BUT FD NO MARK OF POST DESCRIBED BY HUNTER

6/12/87 ACCEPTED IRON SET BY McGhie & BETTS AS CORNER; SET CIC/P² IN ITS PLACE, SET SURVEY MARKER SIGN & POST 1' NORTH

CONT # 3

1/4 CORNER 1-2 MARION 106-13 #630106 (3)

6/12/81 CONT. RP's

CSD & SPIKE IN SW SIDE 20" BURR OAK S81°E 42.06'

CSD & SPIKE IN NW SIDE 22" BURR OAK N18°E 32.65'

CENTER 32" BURR OAK N2°E 53.1'