8-16-65 C.H.D. reset C/M. after grading
12/11/81 FD 10" CIM TILTED, REMOVED, SET 1" GI PIPE/CAP
Corner (1) in Question
¼ corner. 3-4 Marion 106-13
Field BK 5 p. 48 #630306
4-1878 Hunter. Corner gone. P333 No 327 & 4 Brackenridge.
reset from mea of 2.70 chs. (178.2' taken to ℄ rails
when corner was standing. found old post hole reset
~~no~~ stake ~~and~~ or stone. Note: Drawing Shows ¼ Cor.
To be 3.41 chs. E. of ℄ RR also. 225.06

Corner 2" pipe over stone - C/M now in place.

– Disc in fence post	NdV.	59.32
Disc " " "	W	51.1 (TH. RR note 178.2')
S.Row ~~Ox~~ rail road tracks (south Rgt line 248.57)	S.	~~248.7~~ 184.17
Disc in brace pole	SW	81.98
Disc in power pole # 18924	E	30.52
Disc in power pole # 19042	SE	76.04

Cover

Cor't Meas south to center line W & 14 on sec line
1537.32 total 1937 2642.2 Co HD B88 P73

- Meas 1/4 3-4 north to N 3-4 2581.38-

→ Set 1949 BK 42 P.19-21

1960 B78 P65 JK. set 1/16 cor north. set 1" pipe
Sp on W S PP SW 66.35 — Sp SS PP N & E 35.0

Co. H.D. Sd Bk 75 P.8 — 6-20-1935 2581.92 Gov't meas. + 2.15 2584.07 set by Line from so. & prorated Gov't meas.

Co H D 1937. B88 P73. Meas North 2584.07 = see S 33-34
south 2642.2 10 7-13.

JK. 6-1949. B42 P19. Meas north 2587.8-
Meas east 2624.4
Meas north & N 3-4. 2625.3

11-22-72 used corner as referenced. to set Center 4. Marion will Zap later - set 3/4" x 42" iron at corner = Center 4

1935 C.H.D. Book 75 Pg. 8 - found wooden stake with small boulders around it in the center of the road.

1/4 Corner 3-4 Marion 106-13 (2)
#630306

8-29-1979 Dug down in blacktop road with jackhammer. Found 30d spike and 1" range pole end 8" long close to the location of the CIM found at 16" deep
Set 10" CIM over old CIM in the centerline of the N-S Co. Rd 11 & in line of E-W power poles.
RP's: C.S.D in pp# 18924 East 30.25'
C.H. Disc in pp# 19042 S.E 76.08
C.S.D. in pp# 40293 West 33.37
This corner is not Final - more work yet to do.
6-27-1980 (1980 Remon BK) 1/16 North: Dug with backhoe. Found 1"

pipe (bent over) 6' deep 3.35 West and 7.5 North of the transit nail set in ℄ N-S road and in line with fence East. Left pipe in place. Pipe ⅄ Nail E 7.7 TN SSE 8.25

6-30-1980 (1980 Remon. BK.) ¼ Cor. 3-4: We set up a point at the intersection of Hunters measure North of the ℄ RR tracks and East of the ℄ RR track (taken at the line of the fence West of the CIM) dug down from this point and South. About 6' deep found that the area had been subout so dug no further.

Gale Norris Wm. Jones 1953

57.12 Set post + punch stamp post

Bk. Oak 10 N 32 E 445

Bk. Oak 12 S 27 E 475

1/4 Corner 3-4 Marion 106-13 (3)

1949 J.J. Kerr ties to 1/16th north of 1/4 cor 3-4
#630306

1" Iron pipe set as 1/16 Corner.

R.P.'s

Spud in West side P.P. S.W. 66.35'

Spud in South side Tel. pole E.N.E. 35.0'

1/16th falls 35' north of fence to east.

J. Kerr 1960 Ties to 1/4 Cor 3-4

Spike in P.P. N.W. 35.5'

spike in Center pier of R.R. Bridge - S.W. 149.9'

℄ of R.R. Tracks South 184.18'

Measure North 1323.0 to 1/16 Corner (1" pipe) then 1264.8 north to North Section corner 3-4 (1949 by J. Kerr

(over)

12-11-1981 Found 10" C.I.M. tilted So'ly. Removed and dug down to old C.I.M. (head gone). We set a 1" square Pipe with Cap at road surface which fits ties taken in 1979. Before we dug we found a pk. at the surface which was .35 north of our corner.
5/17/89 FD 1" SQ PIPE/CAP IN ℄ OF C.R. #11

JUNE 1994 FD 1" SQ PIPE W/CAP 2" DEEP. SET REF PT. PK NAIL IN ℄ BLACKTOP DRIVEWAY TO THE EAST.
BACKSIGHT - IN LINE W/PK NAIL IN NLY P.P. OF 2 ESE ±200'.

T@ 1/4 COR 3-4
TO REF PT
VA 88° 15' 34" dv 03
SLOPE 62.625 HORZ. 62.59

1/4 CORNER 3-4 MARION 106-13 ④

11-14-94 SET 1" SQ PIPE W/CAP BY CHD. #630306

Aug 1996 Dean Strange of Peoples Coop Found 2" Disk in Road Surface.