8-2-65 found ½"x2" iron concreted in elaborate fence corner complex which checked with R.Ps left as is (1)

¼ corner 4-9 Marion 106-13 #6 30404
4-1875 Hunter P267 no 265 L9. Andrew Pulte
found small stake in road from marked BT stump.
Corner 56½ lks north of corner of fence south on S side road.
as ground still frozen did not set anything more.

4-1895 Hunter P333 no 327. L4 W. Brackenridge
found remains of stake P207., no meas., no further info.

1927 JK B-3 P37 set center 9 but did not mention if
N-S ¼ line run entirely or not N ¼ 9 not mentioned.

1929 JK B 1 P37 Mentioned ties to N ¼ 9
Nail in 15" brook. SW 3.61 - Nail in 15" brook NW 24.58.

1949 JK B 41 P 46. mxed corner. No desc
oak NW 24.5 Cent 20" elm. NE 74.2.
run line center 9 north. 2632.4. set iron at 1452 as prop cor.
run line prop cor east 2624.09. set M & L 1312.04.
point on E section line 1452.51 from E 1/4 9.

1938 JK. B 12 P 62 & 9 Wm Curson. found stone as corner.
15" Brook NW 24.58 - 15" brook. SW 31.67
run & meas line west 2644.98 set axle shaft M & L 1322.49
RP axle shaft. center steel F.P.N. 30.5 - tele pole. NW 40.03

8-65 project to set C/M - found massive concrete around
new sager corner post for new fence west, with 1/2" x 2" iron bar
concreted into this complex. found. both RPs B 41 P 46 in place.
- Center 15" brook (now 22") NW 24.58 - Center 20" elm (now 30" NE 74.2
both checked favorably with iron - accepted and left as is.
11-21-72. See Center 4 for aerial run north

Card #2

1/4 Cor. 4-9 Marion 106-13 #630404

Gov'T Notes: Oct. 1853 Wm A. Jones Dep. Surv.

39.96 1/2 - 39.96 1/2 Set Post at Qr. Sec. Corner

Bf. Br. Oak 11" N 7° E 222 lks. (Note: BT is stump in 4-1875 T.H.

Made Trench.

4/31/89 FOUND 1/2" x 2' IRON BAR IN CONC. CHECKED RB's (22" OAK 1965) NOW 26" ± 25' NW, 30" ELM 1965) NOW DEAD ± 74.5' NE