#630409 (1)

X

1/4 corner center 4 Marion 106-13

4-1878 Hunter P 333 no 327. S.f. W. Brackenridge.
set stake at true intersection lines.
-16 west set stake M&L. 20.12 (1327.92' to stone.
- north. 39.12 total (2581.9' 2655.84 1/2 mile.
- found center RR tracks to be 10.35½ (683.43' from N 1/4 4.
- " NRWRR " to be 9.38 (619.1 " N 1/4 4.
(note. 6-1969. after resetting N 1/4 4 by known RPs after grading
mens above as check found both mens as near exact as possible
without line.

1948 JK. B 38 P 64. used corner fence post.
run & mens line west to stone at W 1/4 4. 2642.6.
noted that stone lay at 1316.6 - could be either from
east or west (See over) M&L. seemed set at 1321.3 ? (over

6-1955 Co H D. B75 P8 used corner post. (Fred Trapp)
Meas east 2621.8 To wooden stake & boulder & road.
Meas west 2655.3 To stone 1/4 4-5 ??

Cont B38 P64 found stone 1316.6 from W 1/4 4 (not used)
set point 660.65 east of W 1/4 as Hunter 2655.84 and
J Kerr 2642.6 from Center 4 west. and stone found at
1316.6 from W 1/4 4. would make stone to center 4. 1326.0
very close to Hunters meas of 1327.92 counting usual Hunter
off meas. then W 1/4 4 would be. at 2652 or about 10' west.

11-21-92. Ran careful line from E 1/4 4 on 35' offset west
taking a random 35' some 800 north toward center 4. this
line fell about 36' ± west of fences N and S where US 14
crosses line as run: line fell almost exact 35' from where
page long accepted corner post as Center 4 would come if set
Lucas & Vertical

Card # 2. Center 4 Marion 106-13. #630409 (2)

believe large post very near true center section 4
at least for E-W. the N-S clearly visible could be
easily tested. projected line north moving offset 80'E
or 45'E of true line as run. line of fence diagonately
running easterly. at railroad east some. 5'± (57.71 on L)
at 1/4 of fence south fully 12' or more. too far east. for 45')

11-24-72 found positive limestone at N 1/4 4.
6.17 west 1 C/N set at C H D corner. (used many years).
11-27. reset 5/8" x 42" iron to come at corrected true intersg
lines all 1/4 corners not positive. as found true 1/4 4-5 (11-22)
- corner (up 4") about 18" north & east of fence wires
of corner post leaning SE at least 30°. .5K

Note 40 D set 80'E

over

¼ random. 35' ⊕ west. now. 41.87 east ¼ iron.
¼ used to Tap north 40 ⊕ lies 1.75 south ¼ line (¼ line)
Rock in corner post 1.13 west ¼ N-S ¼ line.
Will Tap. Meas E-N-W. later.

---

oct, 1857 John Fellows Pg. 41 No. 63 shows measurements
N.W¼ N.W¼ Sec. 4

5-3-82, 1/16 West: Dug from a point 4' West of the traverse nail; West 1'+, East 1'+, and North 3½'. Found nothing. M&L to the Center 4 was appx 4' West and 1½ N. of the t.n. set on the N. side of the c.p.. We dipped for Kerr ½" iron which would fall appx 2½' East and 4½' North of the t.n. Did not find it. (could get deg here a little further South)

5-3-82, Center 4: Dug from a point ½' South of iron here, West 1'+, East 1'+, and 4½' North by 1½' deep to sand subsoil. Found nothing. Left iron in place.

(need to dig South yet!)