5-23-1963 set C/M in place of pipe. (1.)
10-1-79 1" sq x 12" pipe with cap #630605
Section corner west 6-7 Marion 106-13
east 1-12 Rock 106-14.
6-1896 H Fraser by Hunter P 603 no 548 & 6 Hulbert Brackenridge.
found stone set in previous survey where orig. cor. stood.
- Meas north. 39.86.

5-1963 J Kerr set C/M in place of pipe as corner.

Sp	14" oak	N	70.1
Disc	power pole	NW	57.8 (Probably gone)
SE corner	house foundation	NE	78.15

(over)

3-2-1979 Co. Surv.
found ½"x12" pipe over broken CIM., removed pipe
Set another CIM over broken CIM. and Took
R.P.'s - Co. Surv. Disc in P.P. - S.S.E. = 20.68 65'
S.E. Cor. of House fdtn - N.E. - 78.20 95'
Co. Surv Disc in N.E. side of new P.P. - N.W. 59.43
Corner lies ± 5' So. of ℄ Blktop E-W Road.

9-4-1979 Co. Surv. - used Sewer & Water
Contractor's dozer To remove monuments and
locate lower Monument if any. Found That much
digging evidently in the area of the monument as
Soil and rocks were found down into clean yellow sand.
Most of digging To West side of Monu. location and down
about 4.5 ft. from present Road Surface. Also
found a 5/8"x33" Threaded iron rod = 1.9' N. & 0.1' West
of our Monument location.

See card 2

Section Corner West 6-7 Marion Twp 106-13 (2)
East 1-12 Roch. Twp 106-14
#630605

Co. Surv. 9-4-1979

dug by hand below 5/8" rod and found nothing add'n. Dug below Monuments (IM) and found rust spot or discolored spot into clean yellow sand. Spot about 1 inch in dia. with Tapering Size as I went deeper. This spot about 0.2' N. of Monu. location. Accepted Monument location as Section Corner although I could not locate Stone Monu. found by W. C. Fraser, Too much digging went on at this location. (over)

San. Sewer construction This day or the next will destroy all evidence of this corner location. Manhole will be To the East so that a monument can be reset when all construction is complete.

10-1-1979 Set a 1" sq x 1' pipe with cap in new blacktop from R.P.s taken 3-2-1979. Corner now 5½' South of ℄.

See 1979 Remon. Book Pages 2-3, 5, 143, 144, 164

June, 1856 Thos. Hunter Pg. 10 No. 16 Shows Sec. Corner.
1/16 South 19.93½ chs. M&L to 1/4 Post
1/16 East 18.77 then 20.00 to 1/4 Post - B.T.'s (S 39¼°W 10 lks.) & (S 52°E 6 lks.)

Section corner West 6-7 Alamo 106-13 13
East 1-12 Richardson 106-14
#630605

Gen'l Notes, Wm. Jones 1853

30.00 Set post to corner section of 1, 6, 7, 12
Bearing 10 N 0° 30' W 212 lks
" " 14 S 10° W 450 " "
" " 10 S 60° E 66 " "

Dog creek (6KB pg 566)
7/10/45 C.A. Armstrong found 5/8" threaded iron rod which was set by A.C. Smith about 1939 when he surveyed north of corner. There was a doubt in my mind as to the accuracy of rod so dug a hole 3' deep and 4' in all direction from rod, found nothing Set 3/4" pipe 4' long by line and distance east 1/4 12 over 1/16th corner 1317.8 thence 1317.8

cont'd

7/10/45 cont corner set was 469.3 east of notch and nail found in center line of pavement which fits Kerr's distance from 1939. Also corner is on line and 234.9' north of 3/8" iron which is the SE corner of Florence Volz parcel.
While we were working here Thomas Fraser (Surveyor) which owns land SE of here that in 1928 or 1929 he dug here and found a 2" square stake with slim stone 1½' long beside it, and that was the stake set by Hunter in 1887. Also said he placed his corner post exactly 33' South, post now only 32'. (Pipe is 2' south of rod set by Smith)

5/8/34 John Kerr found limestone as corner measured west 469.3' to centerline of highway No. 20; 52 (bk B pg 452)