#631104 (1)

6-6-1962 set C/M. over iron.
10/26/88 REMOVED C.M FOR ROAD GRADING

1/4 corner 11-14 Marion 106-13.

6-1898 Jr Fraser P631 No 571 S 14. G Marquardt.
found unrecorded corner set by Hunter that stood 2 lks E and 2 lks N of corner fence post.
- found stake between 2 posts used as corner
- set new unmarked stake.
- 16 east set small stake N & L 20.00 for line south - run full mile on this 1/16 line set stakes at 19.92 1314.72 each or 5258.88

1941 J Kerr B26 P60 -
Meas S 1/4 9 east to N 1/4 14 (undescribed) set NW 14 at 2630.27 from N 1/4 14 and 7892.94 from S 1/4 9. a stone.
- 16 west shown as N & L 1315.13

over

16- west set 3/4" pipe Midway 1315.13 and at point 2628.45 from 1/16 cor on S line of NW 1/4 14. which was a brass pipe set 1316.16 from W 1/4 14.
RP to 3/4" pipe set - 4pin brac post SW 30.8'
4pin 16" R oak SE 30.5

6-1962 J Ker. B85 P47. L 11-12 Rubow & Lizer.
run line LW 12 west - dug extensively found stake and bark in sand subsoil with piece of iron chain bket etc -
set 1/16 cor line N & L 1318.18 - 1/2" rod sp in PP SE 52.6
sp in guy P NE 65.0
- set C/N. over much debris -
Center 14" turn oaks. N 5°30' E 24.7.
Sp in power pole. S 51° E 37.8.
- run line north set 1/2" rod as 1/16 cor at 1321.83 N & L
which came 7' W of tree line west and 2' W of north-south fence
- also run line east of this 1/16 rod 2630.8 set rod N & L

#631104 (2)

1/4 Cor. 11-14 Marion Twp 106-13

Gov't Notes 10-1853
West on True line between 14 and 14
39.97 set post at Quarter Corner
Br. Oak 8" N62°W 202 = 133.32'
Br. Oak 7" S 42°E 53 = 34.98'
79.94 Sec. Cor.

1/10/80 Found CIM standing 13" deep, but head was broken off. Broke off 1st section and set a new 16" CIM over the remainder. The corner is 1' South of the line of fence West, in line with fence South, 2' West of true line (with fence) North and 11' North of ℄ of Road East. at the 1/16th East found ½" rod believed set by Ken in

1962. Rod 13½' East ℄ Co. Rd. 19 and appx in center of road East.

RP's to CIM

- CSD in East side 24" base to twin Burr Oak NNE 60.91 (1988)
- Spud in NE side pp # 16224 (up 2') SE ~~38.38~~ 38.40 (1988)
- CSD in West side 8" post (up 3½') in fence line South ~~29.51~~ 29.49 (1988)

Gone [illegible] Wm Jones 1853

59.77 Set [illegible]

B Oak 8" 62 W 72

" " 7 3 42 E 53

10/26/88 TIED OUT CORNER FOR ROAD GRADING (REMOVED CIM)
NEW RP C.S.D. IN LARGE C.P. S.E. 62.35'

3-26-99
KPA JPS BB

"631104"	1/4 COR	11-14	106-13	MARION	
FOUND REMAINDER OF KERR'S CIM				DOWN 1.7'	
IN GOOD CONDITION. ONLY TWO TIES REMAINING					
CSO IN EAST 24" BASE		TWIN BUR OAK		NNE 61.04	
SPUD IN NE SIDE	PP# 16224	(UP 2')		SE 38.32'	
CSO IN	PP# 16224	SE 38.34'			
THE CORNER FALLS ON S SHOULDER				OF 19TH ST SE	
14½' S OF ℄	ON CURVE	& 33'		E of ℄	
WHISPERING LN SE SOUTH.					
PUNCH HOLE IN	E END	30" CMP		SW 23.07'	

3-26-99
EPA JPS BB

"631104"E 1/4 COR 11-14 106-13 MARION

FOUND REMAINDER OF KERR'S CIM DOWN 1.7'

IN GOOD CONDITION, ONLY TWO TIES REMAINING

CSD IN EAST 24" BASE TWIN BUR OAK NNE 61.04

SPUD IN NE SIDE PP# 16224 (up 2') SE 38.32'

CSD IN PP# 16224 SE 38.34'

THE CORNER FALLS ON S SHOULDER OF 19TH ST SE

14½' S OF ℄ ON CURVE & 33' E OF ℄

WHISPERING LN SE SOUTH.

PUNCH HOLE IN E END 30" CMP SW 23.07'

(4)

3-26-99
EPA JPJ BB

"631104" 1/4 COR 11-14 106-13 MARION
FOUND REMAINDER OF KERR'S CIM DOWN 1.7'
IN GOOD CONDITION, ONLY TWO TIES REMAINING
CSD IN EAST 24" BASE TWIN BUR OAK NNE 61.04
SPUD IN NE SIDE PP# 16224 (UP 2') SE 38.32'
CSD IN PP# 16224 SE 38.34'
THE CORNER FALLS ON S SHOULDER OF 19TH ST SE
14½' S OF ℄ ON CURVE & 33' E OF ℄
WHISPERING LN SE SOUTH.
PUNCH HOLE IN E END 30" CMP SW 23.07'