#631206 (1)

6-5-64 set C/M. in place of boulder

¼ corner 11-12 Marion 106-13.

12-1910 Chas Larson P142 B 12 Rubw, Trapp, Wal.
found boulder set limestone.
-16 North set iron stake M & L 20.00

1946 B 30 P 52 found boulder under fence no corner.
1953 Caplan B30P52 found boulder gone but stone chips and impression of corner as it had laid.
1962 B 85 P 45 Meas south 2641 set 1/16 M & L 1320.5
Meas east 2630.14 set 1/16 M & L 1315.07
Meas west 2625.2 set 1/16 M & L 1312.6
Meas north to highway non accepted as 1/16 cor. 1318.9.
(over).

1964 B89P70. found MHD RW iron on N side
W & 14 to be 6.23' west of direct line.
Could have set iron at proper place. (land very boggy)
– C/M line nearly under fence running east
or slightly south, about 3'± east of fence running N.
– center 15" br. oak W. 4.7'

Gov't Notes: Oct. 1853 Wm A. Jones Dep. Surv.
N. 40.00 ch. Set Post at Qr. Sec. Corner
B.Ts Red Oak 5" N87°E 45 lks
Br. Oak 4" S62°W 126 lks

1935 - C.H.D. Book #87 page 73 Found boulder in center of pile of small limestone on line with east & west Fences. measure South 1320' to 1/16 Corner (Stone found.

#631206 (2)

1/4 Corner 11-12 Marion 106-13

6-21-82, 1/16 North: Found T.H. 14 R/W monument lying down appx 6' W'ly of McHtire pipe and cap. Both appx 50' North of ℄ T.H.14. Dipped all around but could not find Larsonic iron. The R/W monument would be in line with the fence South on the South side of the highway and the R/W map shows the fence went East here also.

WEIBY 1/4 COR 11-12, DUG FROM 9' TO 13' WEST OF KERRS CIM TO 4' S. OF E-W FENCE & 2' N. OF E-W FENCE. DIGGING TO COVER LINE FROM NW 12 (IRONS FD) OVER T.H. 14 N. R/W MONUMENT (WHICH WAS OLD 1/16 FENCE CORNER). FD NOTHING