#631404 (1)

5-28-65 set C/M over pipe.

1/4 corner 14-23 Marion 106-13

5-1884 Hunter P389 No 380 S 23 Anderson & others.

Corner gone, B trees gone no evidence of knowledge of corner.

- ran & meas section line carefully
- set stake M & L 39.93 (2635.38'
- 16 south set stake midway 19.99 (1319.34'

6-1898 W Fraser P631 No 571 S 14. J Marquardt.

found stake P389 set long stone by its side.

- 16 east set stake M & L 19.95 (1316.5' which came.

11 1/2 lks (E 7.6') and 56 lks (S 37') of corner fence post as mplec.

- ran line above 1/16 north 1 mile to true 1/16 corner on N line setting stakes every 19.92 chs (1314.08'

(over

12-1941 J Kerr B 26 P60 S14 Peterson
- ran and meas line from SW 14 east found stone P631 at 26 34.4

11-1961 J Kerr B 84 P 39 S14 C Sack
- ran & meas line from SE 14 west found corner set pipe 2634.47
- set or checked 1/16 cor N 7 L 1317.23.
- ran line north from 1/16 above. set 1/16 N 7 L 1311.0.

5-1965 - set C/N over pipe to preserve corner.
- nail in hub on bigbt boulder 10" dia WNW 34.75
- " " " on knarly topped br oak good size NE 57.1
lines with fences east and west and north
also brushy fence line south (poor fence).

-16 south 11-69 B101 P 49 on running line west from 1/16 cor S of NE 23 at computed angle 90°33' to N-S 1/4 fence found stone 2.3' south of corner fences N-S-E. could not dig. could be 1/16 corner. (boulder 6"x8" oval top quite straight and long

1/4 COR 14-23 106-13 MARION #631404 (2)
12/31/86 FD CIM SET LATH, BOTH BT TAKEN BY
J KERR IN (1965) STILL STANDING

1/16 E OF 1/4 COR 14-23
12/31/86 FD 1/2" IRON .8' SW LY OF G.R. TO FENCES
N & E & FENCE ROW So.

1/4 corner 14-25 [illegible] 100-43 #631404 (3)

Govt Mon. Wm. Jones, 1853

Mon. in pit at quarter sec. corner

Red Oak 6 N 67½ E 18

Bur Oak 6 S 49 E 81