#631406

1969 corner considered permanent.

1/4 Corner 14-15 Marion 106-13

No record of corner. —
Corner now 3" pipe well above ground very battered.
NE corner. Lester Clark lands.

12-1941 J Kerr B26 P60-62 A Peterson
run line SW 14. to NW 11 set 3/4" pipe as 1/4 14-15 1/4 dist.
2633.21. on meas from SW cor 14 to NW cor 11. and on
line SW 14 as found and NW 14 as set.

8- 1970 Co Surv. road to be graded over corner "likely"
and could be lost. tied existing corner in as follows.
- set 120 100' west than 435.5 both from pipe as .00

(over)

these corners in line with property corners west
Corners to be protected by Lester Clark.
-16 D on S side 8" pin oak N 73°30' W 102.55
- punch mark on p.p emblem up 4' on E side.
power pole # 16089. S 14°30' W 130.15

Govt Notes Wm. Jones 1853
40.00 Set post at quarter sec corner
Planted charcoal & mds mound, pits, & bearing
Planted bearing trees NE & SW.

1/4 COR 14-15 106-13 MARION
12/30/86 FD 5/8" IRON DOWN 4" IN BLACK TOP
TWP RD.