11-15-1962 set CIM over orig corner location.

10-3-83 fd. ¾" Iron

¼ corner 17-18 Marion 106-13 ①

#631706

4-1882 Hunter P 376 no 367 L17 A. Stebbins

Corner gone. B trees gone. - Corner seen many times in center road and direct line of fence running east. - set marked stake at that point. - Meas to center road running southeasterly 6.50 (429' - Meas south to SW cor 17 39.96 (2637.36'

4-1898 H Fraser P 622 no 565 L18 J Smith E Kiene

found stake P 376 also stump & SW BT, proved correct. lines with corner past east of road and fence line further east.

(over

set stone on each side of stake brought up to level of road surface. B.T. 8" beak N 88¼ W 86½ L. (5761'
-16 north set stone & stake N & L. 19.97 (1318'

10-1946. J Kerr B 32 P 34 L 18 Roy Daniels actually found stone 3-46 B 28 P 58.
found stones etc set iron pipe riser
-60D elm tree NW 113' — line Ppole N & S E 25'
-set pipe south in center road running southeasterly 439.8
-RP pipe sp PP NNE up 4' 40.5 each side pole. B 55 P 13.
sp PP L E up 1' 49.5 " " " angle 180° 13.5' in P8 - N 89° 32.5' S 90° 14'

9-1951 B 52 P 59. L 18 R Daniels. 1322.55 west to 1/16 corner
in creek edge - also corner in road 233.45 south. See B 98
-B 33 P 4 mine to center 17. 2641.9. P 12 for RPs
11-1962 set CIM sp PP NNE 134.1 Vandal road.
SW cor garage foundation ENE 132.35

1/4 corner 17-18 Marion 106-15 #631706 2

Geo. Nims Wm. Jones, 1853

40.00 Dec post at quarter sec corner

B-Oak 10 S 51 W 55

Red Oak 6 S 31 E 155