X - C.I.M. set by M.H.D. crew 6-14-1974

#631905

section corner west 19 - 30 Marion 106-13
east 24 - 25 Rock 106-14

No records -
120 D - 3' below ground south of fence corner 5.5
lath near corner - corner in doubt - no memory of it.

Corner reset by M.H.D. Crew after extensive elec. Trav. and after comparing data To old T. Hunter road survey record. in Hunter's Road Book p. 102.
Corner falls near Cor. fe. post (see Chart of Cor. Location)

Cor. Nov. Ms Sons. 1853
30 ch. Set post and stone - found rock to S.E.
19, 24, 25, 30. Bo. W. mound of rock. Planted
S.E. Cor. Orig. N.E. [illegible]

Alter 1/4 19-30

T19N R19-30E 32

7/2/89 FD CIM 2" BELOW SURFACE AT FENCES N-E-W, CIM IS 0.87' NE OF NE FACE OF C.P., SURVEY MARKER SIGN ON S. FACE OF C.P.