4-30-1969 set C/M over 2½" x 14" pipe in place of rod. ①

NOTE: see unfinished cert file (#632184)

¼ corner 21-28 Marion 106-13.

5-18 72 Hunter P198 No 208 S28 & 33 J Shehan F Andrews

Corner gone- NE B T standing - a point agreed by Mr Phil Cavanaugh exactly where orig corner stood came within 1 link of B T distance and within 2 links of midway set ¼ post at that point

- meas East 39.76 (2624.16 to stone

- meas West 39.78 (2625.48 To stone

~~4-13-46 B32 P4 accepted fence corner post as corner~~ Set Cut to 2

5/8" x 2' rod in place long used by surveyors and state highway as corner - set by M'Shie ?
Minn Hwy Dept over.

- Meas east prorea corner for E-W 2625' R2624.16.
4-30-69. J Kerr on Campbell survey.
found rod set C/M over 1"x14" gab pipe with
10" square limestones on W & N sides many stones at
bottom & sides - corner just east of deep erosion
gulley. in line main fence south - 5' south fence east
which is very crooked.
- M H D disc in white fence post at bottom S E 2.9' } old
- " " in fence post S side 5' N & E 26.4. } ties.
- " " " " " S 26
- 1/2" pipe under fence south 50' up 1"
- 1/2" " " " 5' N & E 50'
- 1/2" set pipe as prop corner east 566.3 as S W cor 10 acre tract

1/4 Cor. 21-28 Marion 106-13 #632104 (2)

Oct. 1941 A. Armstrong – personal Book 3 p. 53
fence corner has been inplace at least 60 yrs.

9-2-1980 1/4 Cor 21-28: Found Kerr's CIM with piece of limestone standing on the NW and SW sides.
RP's: Bolt (up 6") in R/W sign post with survey marker sign ESE 1.54
CSD SW side corner post in R/W fence NW 5.99
The monument is appx 1.2 SW'ly of the line of the R/W fence running NW'ly

Govt Works, Wm Jones, 853

39.89 1/2 Sal pins at points shown

Br-Oak 8 N 53 E 118

Br-Oak 5 S 38 W 14.

6-8-89 C.I.M. at surface with two pieces of limestone standing on NW & SW sides; bolt (4" up) in R/W sign post with survey marker sign E.S.E 1.56; C.S.D. in SW side of corner post of R/W fence N.W. 6.25
