7-22-64 set C/M over 1/2" x 18" rod

#632106

1/4 corner 20 - 21 Marion 106-13

5-18 59 Hunter P60 no 86 SE 1/4 20 NE 1/4 29.

used corner - set 1/16 west M & L 20.00

Meas south 39.92 (2634.72'

9-1946 J Kerr B32 P5 L21 Vern Day.

found iron 3/4" in 3/4"x40" place. in fence corner, lined fence east and checked by meas did not question corner further.

-16 east set 3/4" pipe M & L 1314 to iron set as center.

RP 1/16 12" br. oak. SW 12.65 - 8

center 14" br oak east 4 south in fence 38.5

over.

B 36 P 32. NW 21 south 2626.64 - set iron M & L 1313.32

Corner used in Sturdevant Surveys.

7-22-64 set C I M one 1/2" x 18" rod.

Lath	36" willow	NE	38.35
"	12" boulder	N	9.85
"	24" willow	W	28.7
Steel post		E	1.0

RR tie corner post moved to place C I M properly

Oct. 1941 A. Armstrong - personal Book 3 p. 53

Set 1/4 Cor. M. & L. (3/4" iron rod) after digging hole

Disc. in Willow - East - 30.2

Disc. in 24" Elm - S.E. - 84.8

Meas. N-S 2634.3. Also set 2"x2" Hub at 1/16 Cor. South

1/4 corner Marion 16-15 1/4 corner 20-21 L2

Govt Mound W.M. Survey, 1853 #632106

40.00 S.E. post of present section corner

Bur. Oak 6 Sz F2y

pole trough

6-8-89 C.I.M. at ground level in woods retook old ties
(willow to NE had fallen)

18" boxelder 9.76 N (tie taken midway between two spikes)
in blaze

45" willow 28.9 W (MHD in south face)

13" boxelder 26.79 S (C.S.D. in blaze west face)

post & sign 1.0 E
