#632205

9-21-1963 set C/M above ½" rod in place of pipe. (1)
6-24-70 removed for shading 4-18-72 reset flush in bldg
section corner. 21-22-27-28 Marion 106-13

5-1892 Hunter P198 no 208 & 28 & 33 J Shehan, Fandrwe.
found stone planted as corner: witness trees NW & SE standing
seemed 5 lks too far north for SE BT, 5 lks too far south for
NW BT. trees near straight line over corner. I the officer
accepted stone as found. being a mean between good notes.
- meas west to corner set by I Bliss and testimony of P. Cavanaugh
39.76 (2624.16' thence 39.78 to NW 28 (2625.48'

6-1892 Thos Fraser P492 no 466 & 27 J Dick, V Dunnette.
found stone P198 - meas east 39.96¼ (2637.5'
-16 south set limestone M & L. 19.98½. (1319.0

1930 J Kerr B 3 P 35-39 town board. 27-28 33-34.

found limestone - mine south 2640 found ½ 27-28

2-1953 J Kerr B 56 P 26 - 800.43' north to NRW 52 on ass line. pavement AZ 126°42'

1960 J Kerr B 81 P 18 Run line north 800.43 to north line RW highway 52. for lots east.

~~1964 B 88 P 30 mine~~ SW 22 east to Pavt. RW 953.05' & 1125.9.

9-1963 set C/M with ½" rod below. now near 10" deep.

Sp.	oak	SW	41.0 ✓
"	"	W	74.6 ✓
"	fence post	NE	43.6.
"	" "	SE	59.45
"	" "	W	35.32

These Ties all gone 4-18-1972 RB.

1946 B 32 P 4. dug for and found that corner had been destroyed. reset ¾" pipe with ½" rod near by RPs. marked ✓

#632205 (2)

Card # 2 21-22-27-28 Marion 106-13

CoHD. B281 1963. found 3/4" pipe.

Meas north to ℄ hwy 52. 676.55
Meas north to 1/4 21-22 2635.96

6-24-1970 co surv removed C/M for grading operations.
set 1/2" x 2' rod over original rod below C/M.
- C/M set by state as RW Marker E 89.44
- iron rod just east of large oak W 74.6
- set 5/8" x 20" rod on a℄m. line from C/M to edge conc block on S edge window opening, or 6.55' N ℄ conc edge window. at 136.0' then 186.75' to conc edge by window.
- angle setting on section corner from C/M as E RW. E by N to window edge. 141°34'

(over

4-18-1972. Co surv. reset C/M removed 6-24-1970...
could find no sign of anything but 40 D spike which
checked within .03 West & .05 N of reset location.
- corner comes on E edge. Black top.
- set 1/2" x 18" rod below
- all ties to house in place
- 89.44 E to C/M type R/W mon
- 91.0 W "
- transit line from E R/W mon over corner reset falls
1.12 N of W R/W mon.

1941 - A. Armstrong - personal Book 3 p. 53 - (From C.H.D. Book # 71 Page 3)
found stone in & Rd from Ties (Co. Rd - Job L 33C)
Ties spk in OAK - W. 74.6 — spk in OAK - S.W. 41.0
Meas. West 2624.4 Thom. 2625.4

Section corner 21-22-27-28 Mon., 196-15 (3)

Govt Mon. Wm. Jones, 1859 #632205

30.00 S. sec post of corner to set, 21-22-27-28

Bu-Oak 12 N 58 E 512

" " 14 N 50 W 81

" " 9 S 55 W 62

" " 11 S 43½ E 52½

11/24/89 FD CIM WITH BROKEN HEAD, E CO. RD. 36 WEST 11.2', CSD IN TRANSMISSION POLE EAST 61.09'