8-4-1969 found C/M set by Co Hwy Dept. set 3" (1)
GONE ~~rod riser in fresh blacktop level with surface.~~

#632206

1/4 corner 21-22 Marion 106-13.

1½" pipe placed as corner no records

- 8-1969 C/M set by county after grading - riser.

all RPs before & after grading

~~Sp tele pole~~	GONE	WNW	37.9.
" ~~cor fence post~~	5/4/89	E	28.6.
" ~~2nd " " south~~ ¼ corner		SE	42.1.
1963 - ~~Sp fence corner~~		E	34.91.
~~Sp power pole~~		NE	68.46.
1966 ~~Sp tele pole~~		NNW	37.93.

2 rods in fence line east on transit line 100' and 200'

(19?) CHD spike & disc in P.P. NG 88.12' (3/4" rod)?

9-1946 J Kerr B 32 P 5 & 21. Vern Day
set 1½" pipe M & L 2636.25' with 3/4" pipe
E & W 33'

Co H & D B 281. 1963 - found 1"4" pipe. set riser 3/4"
Meas south to ℄ pavement US 52 - 1959.41
Meas south to section corner. 2635.96
Meas north to Cor 15-16-21-22 2637.37

Oct. 1941 A. Armstrong - personal Book 3 p. 53
used E-W fence line as Sec. line

Cor[illegible] N. in Nov. Jones 1853

40.00 [illegible] pace to [illegible]
Bur Oak 14 N 70½ W 22.6

Mon Trench

5/4/89 FD CIM IN E OF C.R. #11 NEW RP'S
87.50 NE TO C.S.D. IN PP # 38218, 60.37' E TO CSDIN
C.P.

1/4 CORNER 21-22 MARION 106-13 #632206 (2)

JUNE 1994 FD CIM 8" DEEP. SET REF PT 1" SQ PIPE W/CAP ON BALKSLOPE STRAIGHT W OF 1/4 COR. Δ @ REF PT.

4 RT PK NAIL IN 2ND PP N OF COR E SIDE CR #11 TO 1/4 COR 21-22

114° 56' 47" dh 02
41° 07' 22" dh 04
73° 49' 25"

74° 29' 48" dh 04
0° 40' 24" dh 05
73° 49' 24"

TO 1/4 COR 21-22
VA 88° 32' 37" dv 01
SLOPE 43.445 HOR 43.435

11-16-94 CHD SET 1" SQ PIPE W/CAP.