Y 5-20-1974 Set a C.I.M. over a ½" x 2' rod
Midway on line 2631.61

#632506

¼ Corner 25-26 Marion 106-13.
cert made 2-18-74

No corner ever found or set.
P706 - 6-1901 R Fraser Meas 2½ miles N & S at this
proportion line betw 25-26 warned be. 5263.1 which nearly
matched meas line betw 23-24 (5262.84' - referring to
- Corner gone to bed rock. 4-1892 P475 T Fraser. (SW 25)
- 1946 J Kerr B 20 P33-34. & E cor 36 E.K. set SE cor 36 set and referenced
to cross in stone west. (assumed later to be 33'
set Corner. 5263.33 south of NE cor 26. Could have
run line south to ¼ 35-36
- 7-1965 J Kerr Meas from NW 25 south in old crooked
abandoned road. set 120 D at 2631.65 with hub on east
edge wheel track set no line. (over

U.S. Interstate 90 will run east from this corner coming from southwest. North line of extreme right of way should be this corner. 12-1969 Massive construction in progress - no knowledge of fate of 120 D~~—~~ gone 5-20-79

5-20-1979

Set a C.I.M. M-L 2631.61 by electronic traverse - took R.P.'s

R/W Pc I-90 South 24.6'

M.H.D. disc So. side cor. post West 39.66

[illegible] 1953

40.00 [illegible]

Nov 1961 M&D dog for corner found nothing set 3/8" rod RD's SRP in corner post W 32.32'; SRP in corner post E 27.90'; SRP in 4" plum NE 29.25'