#632604 (1)

10-30-1963. set C/M. over 2½ x 17" pipe

¼ corner 26-35 Marion 106-13

(T.F. Field Book 8 p.13 set stake farmer instructed to set stone.)

4-1892 2 hos Fraser. P475 no 454 S 36. Ch. Kenney Wm. Beach.

stake set from SW Org Tree BK 8 p.13

Meas from above corner east to NE 36 to set temp point from which to set center 36. no desc of corner

= 119.85 76 chs.

total 7910.6 as N side 36 80.03 gave the line N side S 36. 5~~7~~9~~7~~.~~3~~6 (T.F. Field Book 8 p.275.) leaving 2~~6~~33.24 = east above cor. - corner when in place likely similar to E ¼ 35 a stone placed when Marion originally laid out. no desc

---

1940 J Carr B 20 P 33-34 S 26-27. O'Neill

Meas S ¼ 26 east to corner set as S E 26. 2633.8

Above ~~2633.84~~ 2635.33 this was exact meas from SW 26 east. (over

4-1929 J Kerr B-1 P22-27 corners around Marion. above corner set in this survey - corner now used. Corner of P475 not described likely several feet further west.
- meas ~~N~~E 36 to ~~N~~W 35 10,540' subdivided proportionly
5272.3 east 5267.7 west P475 ~~5277.36~~ - ~~2633.24~~
5275.27 2635.33
Set stone at - 2633.85' M&L.

10-30-1963 corner iron stakes, hay knife, stones.
set CIM over 2½"x17" pipe many stones in area near drive.
Center 22" burr oak NW 47.4
Cor fence post NE 31.4
Dist tile pole W 74.7
Old hay knife blade driven in N-S fence E 25.15'

Gov't Notes: Wm A. Jones Dep. Surv. Oct. 1853
39.98 Set Post @ ¼ Cor. Br. Oak 11" S 31° W 74 lks
Br. Oak 9" N 9° W 42½

See Card #2

#632604 (2)

1/4 Corner 26-35 Marion 106-13

10-14-1983 RwB.

Found Kerr's 1963 CIM about 1' S.E. of mail box post and about 8" deep. Checked Ties:
Center of 30" Burr oak Tree -N.W. - 47.4 ok.
Corner post N.E. - now 30.6'
Center of 10" Sq. Tel. box - W.N.W. - 97.5
Center of 18" Burr oak Tree -W.N.W. - 95.7
Tel. pole -west- is now gone.

10-14-1983 RwB.

It appears that the 30" Burr oak Tree N.W. could possibly be the orig. N.W. B.T. (N 9°W 42½ lks) If it is the orig. B.T.

(over)

Then Kerr's 1929 Corner (same as 1963) is not correct and should be about 20' west and 15' North to be at the B.T.'s position However, since this corner position has been used at Kerr's 1929 location, it probably should be kept where it is, At least until we can dig To Try To find corner referred To by Tom Fraser in 1892.

NW 1961 mHD found 1½" pipe with RR spike on top stone 6d by Kerr & Farmer RPLS
SRP in 14" oak NW 46.9'
SRP in corner post 31.4'