/ 7-2-1981 set CIM on SW side Co. to q. (1)
#632805

section corner 28-29-32-33 Marion 106-13
6-1877 Hunter P316 no 310 L33 Brackenridge.
section corner missing. Mr J. Cavanaugh avers his corner
post of fence was set on org mound. and when fence
was "taken up" he put a stone down post hole to
hold corner. found post hole and stone, removed
stone and set white oak post in place of stone & hole.
-16 east set marked stake M & L 20 to 3 1/4 (1322.31

6-1883 Hunter P385 no 376 L32. Moses Tyler.
found corner post P316. (marked)
-16 south set marked stake M & L. 20.00 (1320.' to stone
(OVER) 1/4 32-33

1930 J Kerr B3 P36 ℄ 27-28-33-34 Marion twsp.
Measured from 4 ways to set section corner 27-28-33-34
which was gone at that time. — 2619.16 north to stone
found at 1/4 27-28 — 5273.94 south to stone at south
sec cor 33-34 — 5272.6 east to NE cor ℄ 34.
5274.9 (p.36) or 5279.4 (plat) west to above corner post.
— plat shows 5299.4 notes show 5274.9. No search was
made for corner around corner post.

5-1952 J Kerr B55 P16 ℄ 32 Lithrup Nielson
Meas from corner found ℄ E 32 north to corner post
5283.75' then found broken limestone as recorded in mark
where it lay when in place at Midway 5283.75' No mention of line.

Section Corner 28-29-32-33 Marion #632805 106-13 (2)

9-2-1980 See Cor 28-29-32-33 & Dug from the traverse nail set on East side corner post South 3', West 8', and North 2' by appx 3' deep. Found nothing. We were digging to cover double the line and measure from 1/4 Cor 28-33 (found this survey) over the stake found at the 1/16 West. This point came appx. 9.0 West and 1.5 South of the tin. ~~set~~

Cor Mon. Wm Sec, 1853

BC -- See pos -- -- -- -- -- -- -- -- -- -- -- -- 28-29-32-33
Depressed chiseled + Plugged chiseled
Scribed N.E. - S.W. S.E. + N.W.
Mon mound, 4 ft. x 4 ft.

7-2-81 Sec. Cr. 28-29-32-33: Set a CIM over an iron rod. Corner 1.0 South of the E-W fence line and 2.6 West of N-S fence line and 2.0 S.W of C.P. to fences N-S-E-W. Set survey sign and post 15 North

RPs: CSD in the North side of a Box Elder clump NE 19.80

Set corner on line S¼ Cor. 33 over 1/16 West (fd. 1980) and as far West of C.p. and N-S fence as possible. 1322.15 since the 1/16 was too far West (1323.18 to ~~1321.49~~ T.H) of S¼ Cor 28 we did not feel we could double the distance.

6-29-89 FD. C.I.M. at surface at N-S-W fe. intrsctn. fe. E no longer standing. C.I.M. is 1.2' So. of fe. W, 1.8' W of fe. N-S, 1.8 SW of C.P.

RPs: spike in No. side boxelder clump NE 19.85'
post & sign 0.6' W