5-27-1965 set C/M. between corner posts ① of fence north, south and east. #632806

1/4 corner. 28-29. Marion 106-13

found original 1/4 post standing in mound in fence line., No mene, used for line east.

5-1965 found long time fence complex of fence east (very old) south (mid old) and north with new large cedar corner post of new fence north. There seemed to indicate that area in hollow between 3 posts as proper area for accepted corner. absolutely no way to test or prove corner except by chain old lines. (over

set C/M likely over iron in this area.
North and south fence lines run on fairly level away from corner - east a older fence a steep, brushy, rough line to bottom slope til it joins road running east and northwesterly, road skirts hill corner about 500 or 600 feet west of bend in road. No fence west

---

Oct. 1941 A. Armstrong — personal book 3 p. 53

fence Corner used as 1/4 Corner.
Meas. North 1320' To Fence West Then 1320 To Sec. Cor. - Set
Corner Mon. Ox Iron, 1956

40" Sec post at corner scribed corner witness corner. Made mound, trench + pits + placed Chiseled scribe N.E. N.W.

#632806 (2)

1/4 CORNER 28-29 MARION 106-13

6-29-89 FD. C.I.M. at N-S-E fe. intrsctn. Only one of the two C.P. mentioned remains. C.I.M. is 0.65 So of C.P. & in line with fe. S