~~9-7-71 set C/M over 5/8" rod found~~ (1)

5-22-87 Set CIC/P² 1.23 N and 4.18 E of CIM (removed at loc of stake) mark Fd. on SE side post hole mark

1/4 corner 29-30 Marion 106-13.

no records in courthouse. #632906

6-1957. 5/8" rod set by Mc Ghee origin unknown

Spike	in corner fence post	east	29.1
Spike	in tele pole	SE	43.6
Spike	in tele pole	NW	41.55

9-7-71. Co surv found 5/8" rod 3' east of east edge traveled road on curve of road in line of fence east - set C/M over rod found. Corner accepted until proven otherwise as no records of original corner known.

over new RPs.

29.1 E to line of east road fence running north.
43.67 SE to spike Tele pole # 9880 (orig RP.)
41.45 NW to Tup cap in p pole # 17687
131.0 S.W. to paper cap in p pole # 17686

Gone N.W. Wm Sims, 1953

No. 2 Set pin in ground south of new, diagonal channel made when road was plowed. Planted cherry trees N.E. to S.W.

5/19/87 1/4 COR 29-30, MARION (CORRECTION OF CORNER) DUG FROM CIM OVER 5/8" SMOOTH ROD (REMOVED) FOR 3½' W, 4' N, 1.6' S & 9'+ E. NATURAL SOIL DOWN 5½' ON W. SIDE OF HOLE, THEN ¼' TO CLEAN CLAY. NOT MUCH BLACK SOIL LEFT. EAST END OF HOLE IN BOTTOM OF DITCH SOMEONE HAD DUG A SMALL HOLE ALONG WEST SIDE OF OUR DIG FD A SQUARED UP POST MARK WITH STAKE HOLE .6 So. & .4 E. VERY BOTTOM OF BOTH MARKS FD NOTHING FURTHER ACCEPTED STAKE HOLE AS GOV'T CORNER SET CIC /P2 COR 1' N. OF FENCE RUNNING E. CONT. ON #2

1/4 CORNER 29-30 MARION 106-13 (2)

5/19/87 CONT. 20' (AT RT. ∠) FROM ℄ C.R 101 ON CURVE FROM N TO SW #632906

RP's POP CAP IN S. SIDE PP # 17687 NW 44.21

CSD IN S. SIDE C.P. ESE 24.61

CIC/P² 1.23N & 4.18E OF OLD CIM LOCATION