/ 8-2-77 CIC
5-1987 Vince Fangman report monument pulled out & gone.
9/13/89 FD 5/8" PIPE/CAP IN PLACE #633004

1/4 Corner - 30-31 - Marion 106-13

9-1857 Hunter P 35 No 56. SE 1/4 25 106-14.
SW 1/4 30, NW 1/4 31 106-13.

used corner.. set 1/16 west at 20.00 then 18.75 (123'25"
Govt notes 18.71 and 20.00

16 west Blues - S 46° W 1.12 - 73.42 S 31 1/2 E 1.05 - 69.3

In farm boundry - No fence south.

7-77 dug from corner post compass West 3', South 3', and North 3' by 3' deep. Found nothing! Diggings centered E-W on 1/4 line projected from the South.
8-2-77 Set a CIC/4' p² on the corner on the line

from the 5¼ Cor 31 (set) over the stone at the Center 31 (found) and in line with the E-W fence. Corner 1½' W of the corner post complex to fences N-S-E-W and on N side of fence West

RP.s: Sp and CSD in SW side 8" blazed Box Elder NW13.80
Sp and CSD in SE side 10" blazed Box Elder SW13.69

Cor't Notes, Wm Jones, 1905

33.7' Dist. pass at ground [illegible]
Bl. oak S N82 W 39.4
" " " N53½ W 35.0

(12) 9/13/89 FD 5/8" PIPE/CAP 0.28' EAST OF E. EDGE OF NEW C.P. INLINE WITH E-W FENCE, FENCE ALSO NORTH