~~7-31-69. set short C/M in new blacktop & road. had to re-run line - old tie gone - strong dip in hole for C/M now.~~
7-26-77 "Courtesy of Co." Rest C/M 1.67 S0 + 7.45 E to C&HD locat. #633204

1/4 Corner south 1/4 32 Marion 106-13 (1)
north 1/4 5 Pleasgrove 105-13.

No records
5-1952 J Kerr could find no corner. Book 55 p.16
set iron rod N & L. 2638.52. on twsp line.

sp Disc large brass pole. NW 49.98.
" " tab pole NE 51.12.
Disc cor fence post SW 57.9 ± posts
" " " " SE 56.4 ± leaning
corrected
RPS 1966.

(over)

7-29-69 corner lost in deep grade & black top — used ties to replace corner with short CIM. put in securely with new black top. - Corner 1 foot west of center road. flush with present surface of road. foul up corrected

9-31-69 found county ties were for assumed point used in road layout not road set M&L in 1952. - Re run and mease line carefully, one shot aerial no random or offset. found true corner to be 7.04' west and 1.44 north of county ties. - pulled short CIM and set at proper location in B Top - Disc in PP NW 43.91 - Disc tele pole NE 57.18 - Disc in Corpost SW 52.3 - strong magnetic dip in hole of CIM. corner lies 8' west center road N-S, in line center road W. corner now 2637.6 M&L formerly 2638.5 heavy chain

Co HD B230 P1 1960 2641.35 - north to center set by JK

#633204 (2)

Card # 2. 1/4 corner S 1/4 32 Marion 106-13
N 1/4 5 Pleas Grove 105-13.

? Question this info

B 230 Pl. Co Hwy D. 1960±
found remains of cedar stake with small limestones standing vertical around it.
RP Disc on fence post S.W. 57.45
Disc " " " S E 56.18
corner is PI Δ 0°30' right going north. Sta 39+08.7

4-27-76 Leg at CHD rod in ℄ Co. Rd #1 E. of CIM. Found rod over hub over hub over stake 1"x2" and small piece of limestone in clear clay. Removed all. Left nail at surface.

"Correction of Corner"

7-26-77 Set CIM @ Co. Hwy. Dept location 1.67 S. and 7.45 E of Kern's CIM (removed CIM and 3/4"x13" rod beneath but still got dip in hole).

RP's: ~~Old disc in cut off telephone pole NE 51.42~~

Old disc in corner post SE 59.29

CSD in pp # 44229 NW 131.26

Punch hole top S. end CMP in road W SW 38.37

Govt Notes. Wm Jones. 1853

4/0.00 Set post & dug channel mound stake E. 1/4 section corner. Pits in mound & mound.

Planted S.E. Orange Osage & N.E. [illegible]

9/89 FD CIM CHECKED TIES, CUT OFF TEL POLE GONE, OLD DISC IN C.P. SE 60.18 (POST LEANING SE) PUNCH HOLE TOP S. END CMP SW 38.39

CSD IN RR TIE C.P. NE 60.45'