12-14-61 C L&M set by Co Hwy Dept on rod set 8-61 (#1)
7-26-77 Removed [illegible] & set 3/4" x 13" rod .13S & 4.0E
#633209

1/4 Corner Center 32 Marion 106-13

6-1883 Hunter P385 no 376 S 32 Moses Tyler.
set temp point on exact east-west 1/4 line and in
center old north-south road. for division of NE 1/4 32.
-16 north set stake midway and on this line M&L 2001

8-1961 J Kerr. B84 P12 S 32 Lonny Riddle plot.
set S 1/4 32 M&L 2638.52
found E 1/4 32 - W 1/4 32 accepted cor post as N 1/4 32
run accural lines set 1/2" rod at intersections.
laid out 125' X 265' plot SW of center,
N-S E-W.

OVER.

7-31-69 J Kerr recheck of SE corner plot and house location.
road regraded and RW increased making corner come
in extreme west edge blacktop matt. Co county set C/M
after sub grades searched for corner finally found it.
NW cor of plot and NE corner gone as well as SE.
- found top of C/M down 5" at location above. which
lies one foot ± north of fence west.
- Disc on SE side power pole & tele pole comb. 3' up in tar N.E. 64.95
- Disc on NE side power pole near ground level W N W 35.94
- Center of top of north end small drive culv not marked S S W 89.5

#633209 #2

¼ Corner Center 32 Marion 106-13

7-21-77 Dug 3' E-W centered on point 4' E of Kerr's CIM. Found black mark in clay beneath old road 2' deep. Followed mark down 1' into clean clay. Possible stake hole. Mark appx. 4.0 E and 1.6 So of Kerr's CIM (removed).

This also is at intersecting ¼ lines

7-26-77 Set a ¾"x 13" rod on the E-W ¼ line 1.47' No. of the mark found. Corner .13 So and 4.0' E. of Kerr's Corner (removed). Corner 8' W of ℄ and in line with fence W and ℄ of rd. E

R.P. CSD in pp WNW 39.75'

Punch mark in lug @ N. end CMP in driveway West NW 42.32

9/89 FD 3/4" ROD TOOK NEW TIES
38.81' WNW TO CSD IN PP# 50441
66.28' SE TO CSD IN CUT OFF TEL. POLE
RP TO CMP OK