#633304

9-3-1965 set C/M on line & midway over 16" iron spoke
4-29-69 removed for grading- 11-7-69 reset C&M final. (1)

1/4 corner. South 1/4 33 Marion 106-13.

North 1/4 4 Pleas. Grove 105-13.

5-1892 Hunter P198 No 208 L 28-33 Stehen; & Andrews.
1872 T. Hunter Field Book # 1 p. 15-16
corner gone · dug extensively set temp point M & L 39.99

6-1877 Hunter P316 No 310 L 33 & Brackenridge.
corner gone, dug, again set temp point M & L 39.99.
-1/16 west set stone M & L 19.99 1/2. S 89° 35' E
bearing line north, 1/4 line N 1/4° E

4-1904 Armstrong P112B L4 Mccal McConnel.
found boulder stone pointed on top in north wheel track ones

20 (Corrected 26') north of fence south, east and west.
– Meas east and west 40.10.

9-1965 J Kerr to reset old corners See Card 2. 1952 survey
run line up line from known corners could not find anything at all. dug carefully but maybe not extensive enough
set C & M over. 96" long piece of iron spoke of wheel
limestone on north side, small boulder on South side C/M.
RP center of square bed rail set in fence line NNE 22.95
Spud and Nail in hub on east side large power pole NNW 38.13.
– Meas east and west. 2638.72 on range line
see note 1952 Book 5 B 16
see card # 2.
5-21-1952 S 1/4 33 Found Boulder
Set 1/2" steel by side RPs

#633304

(2)

Card # 2. S ¼ 33 Marion 106-13
N ¼ 4 Pleasant View 105-13

7-29-69 J Kerr removed C/M for grading road. found rod below set rod flush with surface. removed bed rail reference also.
set ½" rod south in fence line at 95' and rod at 145' which corned 1' SE of small oak post securely set in ground these rods on transit line with center of top of east tower transmission line some ⅜ mile south Near due S.

reset C/M

(over

reset C/M.

11-7-1969 found rod set as corner upon removing C/M. also transit rods set south ~~75' and 145'~~ on az line to center top of each trans line pole south.

~~– orig spot in power pole. 37971~~ 6-15-73 gone NW ~~38.1~~

set C/M over rod with stone on S side. 5" dep.

Note – ~~B 58 P 16~~ 5-1952 Moter say found boulder as 1/4 corner and 1/16 stone west 1316.7 where 1/2" rode set by both. yet in 1965 nothing cored or found at S 1/4 33 had to set N & L. 2638.72

– Noting that 1/16 stone set by hunter west 1319.7 from temp point set N & L after digging extensively.

– stone boulder found by C Armstrong who did not find 1/16 stone

6-15-73 74.3 ENE to Cor nail 1/2 high S side trans P 44234

35.7 SSE to Cor nail NE side 10" Cross pat fence cor. corner now 2' W fence S.

1/4 Corner South 1/4 33 Marion 106-13 #3
#633304
North 1/4 4 Pleasant Grove 105-13

4-27-76 Dug W. of Kerr's CIM. Found rust hole believed to be made from rod set by boulder found 5-21-52. Found rust hole 3' deep, 2.1 N and 4.7 W of CIM. Left spike in hole and referenced. Rod location fit line and measure from S. 32-33 cor Kerr's corner at 1/16 W bowl.

R.P.'s CSD W. side brace post SE 39.68
CSD pp # 44234 NE 77.46

4-28-76 (1/16 E) Dug 6'x6' with backhoe ~~[illegible]~~ on line from Kerr's CIM's at N1/4 Cor 4 and NE Cor 4. Point came in ℄ E-W road and in line of fence N. Found guy anchor had been dug in 1'+ (removed) Found stakes.

Govt Notice. Wm. Jones, 1853

40.00 Set post & three wheel stake for quarter sect. corner. Built mound with trench. Planted S.E. Osage Orange & N.E. Apple seeds.