#633404 Card 1

~~9-1-1965 EII2682 Set CIM one stone, 120 D etc.~~ C.I.M

4-7-1976 Removed CIM — found T.H. Stone 0.9 West — Set 3/4x15 rod 0.35 North

1/4 Corner south 1/4 34 Marion 106-13.

North 1/4 3 Pleas. Stone 105-13.

6-1876. Hunter P297 No 292 S34 Brackenridge. Stallwell.

found stake center road. in line fence south - left axis.

9-1884 Hunter P392 No 383 S 3 H Pierson.

found stake P293 in line fence south.

set stone 4x8x18 with broken brick & glass arround bottom.

1/16 east set quarry stone 4x9x18 M & L 19.99 S89 3/4 E

1/16 west set " " with glass arround bottom M & L 20.00 S89 1/2 E 3/4

1/16 south set stone M & L 19.72 1/2 not good proportions N50° E

8-1940 J Kerr B 20 P62-65 & 2-3-9-10.
found stone referenced to cottonwood etc - Meas line south.
1293 to stone 1/16 corner 2597.11 To iron pipe at center 3.
Missed 1/16 stone 4.6' pipe 11.24 and & 1/4 3 19.6' indicating
1/16 stone OK but center pipe too far west.
4-1929 J Kerr B 1 P26 used stone to set SW & S 1/4 35 at 1/3 distance between S 1/4 39 & SE 35 - 2629.7
9-1965 J Kerr to preserve corner.
found stone placed C/M over stone and 120 θ.
1 1/4" pipe driven flush under road fence. & W 51.2 1940 Re.
line of transmission poles south (aerial) E 1.0.
Hub W side brg PP (Trans line) & 28.85 -
corner lies in center road. In line fence running N.
" " 4' south of direct line - Meas East 2629.85 - West 2639.4

#633404 Card # 2

1/4 Corner South 34 Marion 106-13
North 3 Pleas. Grove 105-13

1932 C.H.D. Book # 64 page 73 Fd stone mon.
also Bk 96 p.3-4 Co. H.D. Measure east to stone monument 2633.8

4-7-1976 Co. Surv. — dug with Tractor To remove CIM. for grading — found CIM. To be set over wrong stone — found T. Hunter 4"x8"x18" L.S. and bricks + glass at 2.6' deep To Top Stone ~ stone was 0.9' West and 0.35' N. of CIM. - Set 3/4"x15" rod for Corner over stone placed much junk and sickle mower shoe around bottom of stone.

1/16 S (4-2-76) Chained 1293.4 S. from Kerr's CIM and found limestone and rod on E side of S. gate post in N-S [redacted] fence. Probed fence line S. of stone but found nothing.

4-16-76 Set ½"x15" rod 200.15 S. on line to P.K. beneath number plate of power pole #38008 on hillside to S. Rod lies .8' W of fence S and 4.6 SSW of corner post to pasture fence NW. (Pasture fence gone.)

9-28-76 R.R. Sp. Ne & CSD E side large cottonwood NW 139.41

Gore Note Book, June, 1955

40.00 Set post & drive chisel mark for gore section corner. Built mound with stones. Placed S.E. Corp. Comp., N.E. Apple tree

#633404 Card # 3

¼ Corner S¼ Cor 34 Marion 106-13
N¼ Cor 3 Pleasant Grove 105-13

8-12-1982, S¼ Cor 34: Found T. Taylor pipe inside cap. Found ½" rod set 200.15 South and on line to P.K. nail in pp. in 1976. Set corner from ½" rod and P.K. Corner came .06 North and .03 E of Taylor pipe. Removed pipe to set CIM. Corner 4' West of line of short fence running South and 1' West of line of p.p. running North and 28.2 North of ℄ C.L. 16.

RPs:
CSD in West side of pp. N 24.25
Pencil in lug at top E end C.M.P. ENE 30.95
Pencil in lug at top W end CMP WNW 29.89
Spike and CSD in E side dead Cottonwood NW 139.49

6-23-1982, S 1/4 Cor 34: Found 1/2" pipe with plastic cap # 6507 in place on corner

Note: The 1/16 W falls in I-90. We believe we dug at the 1/16 E. in 1976 (didn't record) and area was in cut.

9/19/92 County Surveyor fd CIM in good shape ± 28' north of ℄ C.R. 16