6-18-69 set C/M. on direct E W 1/4 line and in line fence north & south. ①

Questionable Corner ? RB

1/4 corner center 34 Marion 106-13. NOT ON E-W 1/4 line

6-1876 Hunter P297 No 292 S 34 Breckenridge, Stillwell #633409

set stake at true miters lines.

16 North set stake 19.95 1/2 (1317.0 N&L

6-18-69 J Kerr. run direct line E 1/4 34 to W 1/4 34.

set Corner on line and in line of fence N&S. much treible always claimed to be on line

- Coke cap in monetrus power pole with massive levers to close circuits # 37987 North 41.8.
- Pepsi cap in power pole # 17300 ESE 108.8

Meas west half only triangulated from 1/16 east on 600' base.
- total 1/2 mile 2637.75
-16 west set 3/4" x 12" rod N & L 1318.87 about 4' east of west road edge
set about 1/2" rod on rise about 1600' south along line fence west
above 16 corner lies 3°± east of W edge road south (main line).
" " " " on E edge branch road west or further S.
- large burr oak in fence at each road edge. about 6'
south to E-W 1/4 line 30.25 nail N.S. oak to corner } RP
61.0 to pipe cap in bg PP NNW } 1/16 cor.
- Center 34. in center road at that point but on south side
main road each on sharp land break not over 150 to 200'
east of extreme R/W of 290, road completely closed. both N 1/4 and
S 1/4 of section are C/M's in case super accurate corner must be set for
N-S line. would cross W of 90 diagonally and N 1/4 in deep wooded valley.
big offset east only practical way to run random aerial line.
west R/W of 290 on E-W 1/4 line - 1/2" rod 724.78 east of 1/16 corner

1/4 CORNER CENTER 34 MARION (2)

106-13

6/22/92 Vince Eangman ran E-W
1/4 line and fd CIM 4.55 South,
John must have made a mistake
#633409

see Ktrv BK 101, P 37