4-13-75 "Correction of Corner" found stone - Set CTH.
~~10-30-1963 set CIM one stone and pipe~~ - note: removed

¼ Corner. South ¼ 35 Marion 106-13 #633504 (1)
North ¼ 2 Pleas Grove 105-13

No court house records - some kind of corner could have been used in layout of Marion Village.

4-1929 J Kerr B1 P26. Run & Meas line from. S E cor 35 west to S ¼ 34 set limestone 3 X 12 X 15 and large red cedar stake and smaller stones on straight range line and ⅓ distance 2629.7. as S ¼ 35.

7-1940 B20 P. 62-65 set Center S2. Pleas Grove. Meas S from S ¼ 35 2592.1 set iron as Center 2.

Cover.

7-68 remac line to find. enter 2 last. found corner at 2592.6'

10-1963 set C I M over orig stone & pipe.

Rec tel pole. N 85° W 29.7.

Rec fence post North gate terminus S 80° E 38.77.

Spnd in R R bridge pier west side S. 283.08

B96 P3 1938 C H D found L S with cross & cedar stake N 60° E 1' deep. ties to tm stone - Sp F P N E 45.4 - Sp F P S E 52.5 - (1929) D T P N W 42.3 - D T P S S W 111.6 - Meas west 2630.9. Meas east 2638.45 to corner set M & L S 1/4 35 & S 1/4 36

JKerr set corner same as used above. JK west 2629.7 & 2630.9

1932 C.H.D. Book # 64 page 73 fd stone mon

Measure west to stone Fd. 2630.5

1/4 Corner. S. 1/4 Cor Sec 35 N. 1/4 Cor. Sec. 2 Marie Pleasant Corner 106-13 105-13

4-1975 Received T. Hunter's Book #14 from Dakota Co. Surveyor (2)

4-13-1975 Found 5"x6"x20" tappered limestone 2' deep #633504
Drove pipe on E. side and put point and scrap
iron around. Corner lies 12.75S and 13.0E of Kirr's
will not set CIM. Dug E ½ of N-S road.
R.P's: ½" rod in pasture on transit tie to tag above
number plate on power pole in pasture NE 104.81
½" rod in pasture on transit tie to nail
in hub on huge oak in gully SE 117.86
59° 47' = X between ½" rods.

104.81
103.80
1.01 SW

117.93
117.86
.07 SE

N(E) .07 SE

Govt Notes Wm. Jones, 1853

1/0.00 Set post 1 link chained south for pine
[illegible]. Bell mound with brick.
Planted S.E. Corner Corner N.E. Mound
[illegible]

8-11-1982, S. 1/4 Cor 35 & Found 5/8" rod at ground surface.
Found 1/2" rods set SE and NE in 1975 but
the oak tree in the gully SE had been cut
below the hub. Set nail on line and measured
from NE and came .16 SE of 5/8" rod in place.
Measured 117.93 SE From nail to 1975 rod
& .07 long. Dug down 30" and found our
1975 spike at the previous road surface.
The spike fit the distance tie to the NE rod but was
.07 SE'ly of nail set at surface and would fit SE
tie rod. Set CIM over 5/8" rod at the location

1/4 Corner S 1/4 Cor 35 Marion 106-13 (3)
N. 1/4 Cor 2 Pleasant Grove 105-13
#633504

8-11-1982 continued, S 1/4 Cor 35: of the old nail fd. This corner .22 SE'ly of the 5/8" rod found at the ground surface.
- Corrected 1/2" rod 104.81 NE'ly .04 SE'ly to be on line to Osmose disc above number plate on pp NE
- CSD in SE side W'ly gate post SW 130.83 Measured 143 1/2 NW'ly to ℄ C.R. 16 on curve Corner lies in ditch ℄ of road farther South Corner in pasture E. of road.

8-23-1982, S 1/4 Cor 35, RWB: Set 5/8" rod from the rods.

9/19/91 County Surveyor found CIM in good shape in Borst pasture.